


**KANE PACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 5457-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Control No.:	Date Issued
0073	250312

Customer	ARKRAY	Attention To	REXEL ALMARIO
Item Code	84-05467A	Department	PRODUCTION
Item Description	INNER BOX F821629-1	Date of Detection	250305
Job Order Number	JO25-M-00773-1	Section Detected	QA SCREENING 5

ILLUSTRATION OF THE PROBLEM

Lot Quantity (pcs)	Reject Qty (pcs)	Reject %
--------------------	------------------	----------

1966	29	1.48
------	----	------

Nature of Defect:

MISALIGN PRINT

Requirement:

7 mm (Tolerance: ± 3 mm)

Actual

Print within the cutting line

ACTUAL: Print within the cutting line.

REQUIREMENT: 7 mm (Tolerance: ± 3 mm)

NO. OF OCCURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN	CONTENT
<input checked="" type="checkbox"/> First	<input type="checkbox"/> Hold	<input type="checkbox"/> Slotter	<input type="checkbox"/> Material
<input type="checkbox"/> Recurrence No.: <u>1</u>	<input type="checkbox"/> Special Acceptance	<input checked="" type="checkbox"/> EQOS	<input type="checkbox"/> Dimension
Date.: <u>250305</u>	<input type="checkbox"/> For Rework	<input type="checkbox"/> Vertical	<input type="checkbox"/> Appearance
	<input checked="" type="checkbox"/> Reject / Disposal	<input type="checkbox"/> Diecut	<input checked="" type="checkbox"/> Process / Method
		<input type="checkbox"/> Detaching	
Issued by	Checked by	Approved by	Received by (Receiving Section)
LESTER JOHN DIOSO 250312	CHARLENE JAN MARIE FLORES 250315	MICHAEL CASILLANO 250317	GERALD DE GUZMAN 250410

I. INVESTIGATION / ANALYSIS**DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)**

System / Training

Design / Toolings

Process / Material

WHY 1 : Movement of print during process

WHY 2 : Delayed timing/feeding of boards

WHY 3 : Warp materials

WHY 4 : Lacking of weight jig



INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)

System / Training

Design / Toolings

Process / Material

WHY 1 : na

FINAL CONCLUSION

CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)

WHO / WHEN

Process / Material

WHY 1: Provision of weight jig to prevent warpage of materials. Existing Paper weight jig already disposed as per advice of Top management ME // 2025-06-15

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)

A. Sorting Result					C. Reworking	
	Location	Total Stock	NG	Total Good	Rework Quantity	na
RM	na	0	0	0	Total Good	0
WIP	na	0	0	0		
FG	na	0	0	0	Rework PPM (Good)	0

B. Orientation			
Date	2025-06-03	Time	12:44
Title	0		
Attendees	na		

Prepared By:	Approved By:
GERALD DE GUZMAN 250603	N/A
	Department Head

**KANE PACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISI II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 5457-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)**

Date Conducted:	PIC:
Identified Rootcause	Recommendation

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked By:	Date	Implemented?	Running	JO Number	Date	NG Qty	Lot Qty
1st Verification of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	1st				
2nd Verification of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	2nd				
3rd Verification of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	3rd				
Effectiveness of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	4th				
Remarks:				5th				

IV. CLOSURE

Status	Remarks		
Still Open			
Approved by:		Process Owner Acknowledgment: (Receiving Section)	
N/A QA Head	N/A Top Management	N/A Line Leader	N/A Department Head
Date: -	Date: -	Date: -	Date: -