KVI	INVESTIGATION REPORT FORM (IRF)								
No. 5 I	Ring Road LISP II, Bro	GE PHILIPPINE INC.  gy. La Mesa, Calamba City, Laguna							
Teleph Fax No	Control No.: 0073		Date Issued 250312						
Customer	ustomer ARKRAY			REXEL ALMA	ARIO	230312			
Item Code	84-05467A		Department	PRODUCTIO	N				
Item Description				Date of Detection 250305					
Job Order Number	JO25-M-00773-1		Section Detected	QA SCREENI	NG 5				
	ILLUSTRATION C	OF THE PROBLEM							
1			Lot Quantity (pc	s) Reject	Qty (pcs)	Reject %			
	1966	:	29	1.48					
	0210	329-1	Nature of Defect:						
		/	MISALIGN PRINT						
			Requirement:						
			7 mm (Tolerance: ±3mm)						
-			Actual						
ACTUAL: Print with REQUIREMENT: 7	Print within the cutting line								
NO. OF OC	CCURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN CONTENT						
First  Recurrence No.:1		Hold Special Acceptance	Slotter Gluing EQOS Vertical		I	Material Dimension			
Date.: 250305		For Rework Reject / Disposal	Diecut Others  Detaching			Appearance Process / Method			
		Checked by			Passivad				
Issued by  LESTER JOHN DIOSO   250312 CHARLEI		CHARLENE JAN MARIE FLORES   250315	Approved by  MICHAEL CASILLANO   250317		Received by (Receiving Section)  GERALD DE GUZMAN   250410				
22012111,011111	.000   200022	I. INVESTIGATION		32 302   233 .23					
DIRECT CAUSE: (A	analyze the reason	of occurence, why it happened?)							
System / Training									
Design / Toolings									
Process / Material	I								
WHY 1: Movement	t of print during proc	ess							
WHY 2 : Delayed ti	WHY 2 : Delayed timing/feeding of boards								
WHY 3: Warp materials									
WHY 4: Lacking of	weight jig								



INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)

## **INVESTIGATION REPORT FORM (IRF)**

Syster	n / Trai	ning									
Design	ı / Tool	ings									
Proces	ss / Mat	terial									
WHY 1	: na										
					FINAL CO	NCLUSION					
CORRE	CTIVE	ACTION: (Actio	ons to be done	to ensure	that the probl	em will not happ	pen again)	WHO / WHEN			
Proces	s / Mat	terial									
WHY 1: Provision of weight jig to prevent warpage of materials. Existing Paper weight jig already disposed as per advice of Top management  ME // 2025-06-15								ME // 2025-06-15			
IMME	DIATE A	CTION: (Action	n to be done to	contain/ t	emporary cori	ect the problem	found)				
A. Sort	ing Resu	ult			_	C. Reworking					
		Location	Total Stock	NG	Total Good	Rework Quanti	ty	na			
RM		na	0	0	0	Total Good		0			
WIP		na	0	0	0						
FG		na	0	0	0	Rework PPM (Go	ood)	0			
B. Orie	ntation										
Date 2025-06-03					Time	12:44					
Title		0									
Attend	ees	na									
Prepared By:						Approved By:					
GERALD DE GUZMAN   250603						N/A					
						Denartment Head					



## **INVESTIGATION REPORT FORM (IRF)**

II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)												
Date Conducted:	PIC:	PIC:										
Ide	entified Rootcause			Recommendation								
III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)												
	Checked By:	Date	Implemented?	Running	JO Nu	mber	Date	NG Qty	Lot Qty			
1st Verification of Action			[ ] Yes [ ] No	1st								
2nd Verification of Action			[ ] Yes [ ] No	2nd								
3rd Verification of Action	n of Action		[ ] Yes [ ] No	3rd								
Effectiveness of Action			[ ] Yes [ ] No	4th								
Remarks:												
				5th								
IV CLOSURE												
IV. CLOSURE												
Status			Ne	Remarks								
Still Open												
Approved by: Process Owner Acknowledgment: (Receiving Section)												
	Proces	Process Owner Acknowledgment: (Receiving Section)										
N/A		N/A		N/A			N/A					
QA Head	Тор М	anagement	Line	Line Leader			Department Head					
Date: -	Date: -		Date: -	Date: -			Date: -					