KAI	NEPACKAG	E PHILIPPINE INC.	INVESTIGATION REPORT FORM (IRF)							
	Ring Road LISP II, Broone No. (049) 5457-7	gy. La Mesa, Calamba City, Laguna	Control I	No.:	Date Issued					
	. (049) 545-6302		0075		250327					
Customer	CANON BUSINES	Attention To	REXEL ALMA	RIO						
Item Code	FX2-4185-000-R	Department	PRODUCTION	N						
Item Description	Z10_BOX-ACC-5	55	Date of Detection	e of Detection 250322						
Job Order Number	JO-F-25-364-1		Section Detected QA SCREENING							
ı	ILLUSTRATION C	OF THE PROBLEM								
(((((((((((((((((((Lot Quantity (pcs	s) Reject (Qty (pcs)	Reject %				
			2000	2	27	1.35				
		1	Nature of Defect:							
			BLOTTED PRINT							
		FX2-4185	Requirement:							
	1_		Acceptable as long as readable by barcode scanner							
ACTUAL: Platto	d print and cappa	ot read by barcode scanner	Actual							
		long as readable by barcode	Blotted print and cannot read by barcode scanner							
NO. OF OC	CURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN CONTENT							
First		Hold	Slotter	Gluing		Material				
Recurrence No.: 1 Date.: 250322		Special Acceptance	EQOS Vertica		A = = = = = =					
		For Rework Reject / Disposal	Diecut Detaching	Others		Process / Method				
Issued		Checked by	Approved	d by	Received by (Receiving Section)					
LESTER JOHN DI	IOSO 250327	CHARLENE JAN MARIE FLORES 250421	MICHAEL CASILLANO 250422		GERALD DE GUZMAN 250506					
		I. INVESTIGATION	/ ANALYSIS							
DIRECT CAUSE: (A	nalyze the reasor	of occurence, why it happened?)								
System / Training										
Design / Toolings										
Design / Toolings										
Process / Material										
WHY 1: Over applic	cation of ink to the s	ubstrate.								
WHY 2 : Accumulat	ion of ink to the edg	es of the flexo plate.								
WHY 3 : Over print impression during adjustment upon trial run.										



INVESTIGATION REPORT FORM (IRF)

INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)											
Syste	m / Trai	ning									
Desig	n / Tool	ings									
Proce	ss / Mat	terial									
WHY 1	: NA										
					FINAL CO	DNCLUSION					
CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen aga							pen again)	WHO / WHEN			
Proce	ss / Mat	terial									
WHY 1: Conducted cleaning of cyrel upon r ndetection. Eqos operator // 2025-03-1							Eqos operator // 2025-03-19				
WHY 2: Provision of reject separator (have list of rejects)							ME // 2025-06-30				
IMME	DIATE A	CTION: (Action	to be done to	contain/ te	emporary cor	rect the problen	n found)				
A. Sorting Result						C. Reworking					
		Location	Total Stock	NG	Total Good	Rework Quant	ity	na			
RM		na	0	0	0	Total Good		0			
WIP		na	0	0	0	Rework PPM (Good)		0			
FG		na	0	0	0						
B. Orie	ntation										
Date	te 2025-06-10					Time		08:51			
Title na											
Attend	ees	na									
Prepared By:						Approved By:					
GERALD DE GUZMAN 250618						N/A					
						Department Head					



INVESTIGATION REPORT FORM (IRF)

II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)												
Date Conducted:	PIC:	PIC:										
Ide	entified Rootcause			Recommendation								
III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)												
	Checked By:	Date	Implemented?	Running	JO Nu	mber	Date	NG Qty	Lot Qty			
1st Verification of Action			[] Yes [] No	1st								
2nd Verification of Action			[] Yes [] No	2nd								
3rd Verification of Action			[] Yes [] No	3rd								
Effectiveness of Action			[] Yes [] No	4th								
Remarks:												
				5th								
IV CLOSURE												
IV. CLOSURE												
Status			Ne	Remarks								
Still Open												
Approved by: Process Owner Acknowledgment: (Receiving Section)												
	Proces	Process Owner Acknowledgment: (Receiving Section)										
N/A		N/A		N/A			N/A					
QA Head	Тор М	anagement	Line	Line Leader			Department Head					
Date: -	Date: -		Date: -	Date: -			Date: -					