KAN	INVESTIGATION REPORT FORM (IRF)							
No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 5457-7166 to 69 Fax No. (049) 545-6302			Control No.:		Date Issued			
Fax No.	. (049) 545-6302		0077			250329		
Customer	BROTHER INDUS	TRIES PHILIPPINES, INC.	Attention To	REXEL ALMA	RIO			
ltem Code	D037FX001		Department	PRODUCTIO	N			
Item Description	CARTON MFC-J43	350DW EU-C	Date of Detection	250326				
Job Order Number	JO-25-IPD-00414	-1A	Section Detected QA SCREENING					
1	LLUSTRATION O	F THE PROBLEM						
100	Р	brother.eu/recycling	Lot Quantity (pcs)Reject Qty (pcs)Reject %1300493.77Nature of Defect:MISALIGN PRINT					
Expanded po		Cet apparell, autocom autocom sea accessione	Requirement:					
free pack	kaging ^{(P) En}	et encloses Construction au voir a publicationenticulut. In Provident la reportation en le dan de voire reported 1	Acceptable up to 5mm print tolerance					
8MM		•	Actual					
		25 MM 7	Exceed printing tolerance					
NO. OF OCC	CURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN CONTE					
First	No.: <u>1</u> Date.: <u>250326</u>	Hold Special Acceptance For Rework Reject / Disposal	Slotter EQOS Diecut Detaching	Gluing Gluing Others	I	Material Dimension Appearance Process / Method		
Issued	l by	Checked by	Approved	d by	Received by (Receiving Section)			
LESTER JOHN DI	OSO 250329	CHARLENE JAN MARIE FLORES 250421	MICHAEL CASILLA	NO 250422	GERALD I	GERALD DE GUZMAN 250506		
		I. INVESTIGATION	ANALYSIS					
DIRECT CAUSE: (Ar System / Training	nalyze the reason	of occurence, why it happened?)						
Design / Toolings								
Process / Material					_			
WHY 1 : Movement	of print during proce	255.						
WHY 2 : Delayed timing/feeding of boards.								
WHY 3 : Warp materials.								
WHY 4: Lacking of	weight jig.							

г



KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Bray, La Mesa, Calamba City, Laguna

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 5457-7166 to 69 Fax No. (049) 545-6302

INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)

System / Training

Design / Toolings

Process / Material

WHY1: na

FINAL CONCLUSION										
CORREC	TIVE ACTION: (Act	WHO / WHEN								
Process	/ Material									
WHY 1:	Provision of addition per advised of top		event warp	oing of material	s. Paper weight jig a	already disposed as	ME // 2025-06-30			
IMMEDI	IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)									
A. Sorting	g Result				C. Reworking					
	Location	Total Stock	NG	Total Good	Rework Quantit	у	na			
RM	na	0	0	0	Total Good		0			
WIP	na	0	0	0						
FG	na	0	0	0	Rework PPM (Goo	od)	0			
B. Orient	ation					·				
Date	2025-06-10			Time		08:40				
Title	na	na								
Attendee	es na									
Prepared By:					Approved By:					
GERALD DE GUZMAN 250618					N/A					
					Department Head					

KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 5457-7166 to 69 Fax No. (049) 545-6302						INVESTIGATION REPORT FORM (IRF)							
II. QA ROOTCAUSE VER	IFICATI	ON (To be fil	led out by QA	ln-cha	arge)								
Date Conducted:				F	PIC:								
Id	lentified	Rootcause					Recomm	endation					
III. CORRECTIVE ACTIO	N VERIF	ICATION (To	be filled out	by QA	In-charge)								
	Ch	ecked By:	Date	Im	plemented?	Running	JO Nu	mber	Date	NG Qty	Lot Qty		
1st Verification of Action				[]	Yes []No	1st							
2nd Verification of Action				[]	Yes []No	2nd							
3rd Verification of Action				[]Yes []No		3rd							
Effectiveness of Action				[] Yes [] No		4th							
Remarks:						5th							
		I	ľ	V. CLO	SURE								
Status		Remarks											
Still Open													
Approved by:					Process Owner Acknowledgment: (Receiving Section)								
N/A		N/A		N/A			N/A						
QA Head		Top I	Top Management			Line Leader			Department Head				
Date: - Date: -			1	Date: - Date: -									