

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 5457-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)


Control No.:

Date Issued

0104

250804

Customer	CANON BUSINESS MACHINE PHILS.	Attention To	REXEL ALMARIO
Item Code	RX1-5732-000-RMFG	Department	PRODUCTION
Item Description	Z10_sleeve_s	Date of Detection	250712
Job Order Number	JO-F-25-846-3	Section Detected	QA SCREENING

ILLUSTRATION OF THE PROBLEM

Lot Quantity (pcs)	Reject Qty (pcs)	Reject %
800	24	3.00

Nature of Defect:

MISALIGN GLUE

Requirement:

Acceptable up to 5mm.

Actual

Misalign glue is up to 7mm exceeds specified requirement

NO. OF OCCURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN	CONTENT
<input type="checkbox"/> First <input checked="" type="checkbox"/> Recurrence No.: <u>3</u> Date.: <u>250222</u>	<input type="checkbox"/> Hold <input type="checkbox"/> Special Acceptance <input type="checkbox"/> For Rework <input checked="" type="checkbox"/> Reject / Disposal	<input type="checkbox"/> Slotter <input type="checkbox"/> EQOS <input type="checkbox"/> Diecut <input type="checkbox"/> Detaching <input checked="" type="checkbox"/> Gluing <input type="checkbox"/> Vertical <input type="checkbox"/> Others	<input type="checkbox"/> Material <input type="checkbox"/> Dimension <input type="checkbox"/> Appearance <input checked="" type="checkbox"/> Process / Method
Issued by	Checked by	Approved by	Received by (Receiving Section)
LESTER JOHN DIOSO 250804	CHARLENE JAN MARIE FLORES 250806	MICHAEL CASILLANO 250807	GERALD DE GUZMAN 250807

I. INVESTIGATION / ANALYSIS**DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)****System / Training**

WHY 1 : Misalign Glue occurs during manual gluing.

WHY 2 : Operator did not make adjustments (hilut) during gluing the item.

WHY 3 : Operator is not aware on the hilot or adjustment on the box during gluing.

WHY 4 : Operator assigned is from Lamination but not an Authorized Manual Gluing Operator.

WHY 5 : Operator and Leader assumed that the operator is Authorized since the process is Manual Gluing.

Design / Toolings**Process / Material**

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 5457-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)****System / Training**

WHY 1 : na

Design / Toolings**Process / Material****FINAL CONCLUSION****CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)****WHO / WHEN****System / Training**

WHY 1: Separate list of Authorized Operator of Lamination and Manual Gluing.

production // 2025-09-04

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)

A. Sorting Result

C. Reworking

	Location	Total Stock	NG	Total Good	Rework Quantity	na
RM	na	0	0	0	Total Good	na
WIP	na	0	0	0	Rework PPM (Good)	na
FG	na	0	0	0		

B. Orientation

Date	2025-09-04			Time	17:33
Title	na				
Attendees	NA				

Prepared By:

Approved By:

GERALD DE GUZMAN | 250904

REXEL ALMARIO | 260427

Department Head

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 5457-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)**

Date Conducted:	PIC:
Identified Rootcause	Recommendation

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked By:	Date	Implemented?	Running	JO Number	Date	NG Qty	Lot Qty
1st Verification of Action			[] Yes [] No	1st				
2nd Verification of Action			[] Yes [] No	2nd				
3rd Verification of Action			[] Yes [] No	3rd				
Effectiveness of Action			[] Yes [] No	4th				
Remarks:				5th				

IV. CLOSURE

Status	Remarks
Still Open	

Approved by:		Process Owner Acknowledgment: (Receiving Section)	
N/A	N/A	N/A	N/A
QA Head	Top Management	Line Leader	Department Head
Date: -	Date: -	Date: -	Date: -