KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302			INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: 264 Date Issued: 20 08 06					
							Customer	SANYO DENKI
Item Code	00939007-01		Department PRODUCTION					
Item Description	CORRUGATED	CORRUGATED CARTON		Date of Detection 20 08 05				
Job Order Number	WO-20-M-01049)-12	Section Detected QA - IN LINE					
	ILLUSTRATION OF THE PROBLEM			Major Minor				
	r	*** *** *** *** *** *	Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage			
9	ARIVO	DENKI	1367	62	4.54%			
		PEINN	Nature of Defect:					
/////		YAYA		SCRATCHES (Scuffing)			
I/I			Requirement:					
				No contamination of ink from other boxes				
			Actual:					
	ί.	90 6000 First Name Sente		W/ contamination of ink				
NO. OF OCCL	NO. OF OCCURRENCE DISPOSITION			AREA OF OCCURRENCE / ORIGIN CONTENT				
First		Hold	Slotter	Gluing	Material			
Recurrence		Special Acceptance	EQOS	Vertical	Dimension			
No.:	_	For Rework	Diecut	Others:	Appearance			
Date:		Reject / Disposal	Detaching		Process / Method			
Issued	by	Checked by	Approved by	/	Received by (Receiving Section)			
Adrian Ver QA-IE St	(Table) i professioner allegatietz felik	Ms. Normi depalda QA Supervisor	Mr. Rexel Alma QA-Asst. Mana	rio Mr. Ø	erald De Guzman			
DIRECT CAUSE	: (Analyze the reason o	I. INVESTIGATI f occurrence, why it happened?)	ON / ANALYSIS INDIRECT CAUSE:	(Analyze the reason of occurre	nce, why it leaked?)			
Why 1: Why 2: Why 3: Why 4: Why 5:	Why 2: Why 3: Why 4:		Why 1: Why 2: Why 3: Why 4: Why 5:					
Why 1: Why 2: Why 3: Why 4: Why 5:	/hy 2; /hy 4:		Why 1: Why 2: Why 3: Why 4: Why 5:					
Why 1: Why 2: Why 3: Why 4: Why 5:	Why 1: Why 2: Why 3: PLS, SET ATTACHED W Why 4:			Why 1: Why 2: Why 3: PLS. SEE ATTAG(ED) Why 4: Why 5:				



SIGNATURE

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

							enten of available	
MAN GARAGE				FINAL CO	NCLUSION			
	OCCURRE	NCE ROOTCAUSE			OUTFLOW ROOTCAUSE			
ITE	nator premove med flat in gen the sec	BELT AND	BECAUS	E OF	-OPENATOR NOT IMMEDIATE NOTICE THE SCRATCHES BECAUSE THE OCCURRENCE IS RANDOMLY. CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again) Actions to be done to eliminate recurrence Who / When			
IMMED	NATE ACTION: (Action to be do	one to contain/ tempora	ry correct the pr	roblem found)				
A. Sorting Re	esult							
	Location	Total Stock	NG	Total Good				
RM	N/A					MZ.		
WIP	N/n				System	N/A		
FG	Aln							
B. Orientatio	3. Orientation							
Date	20 08 11	Time	9:55~	10:06	Design /	N/4		
Title	ORIENTATION REGARDING SCRATCHES OF SANYO DENKI DC929CO7-CI CORRUGATED CARTON		DENKI	Tools	<i>1</i> -7/★			
lees	SEMI-AUTO GUVING							
C. Reworking					vi -			
Rework Quantity N/A								
Total Good		N/A				PLS. SEE ATTACHED		
Rework Per	Rework Percentage (Good)		N/A					
II. QA	ROOTCAUSE VERIFICAT	ION (To be filled o	ut by QA In-	-charge)	Date Conducte	ed: 20 08 10 PIC: A. Vergaya		
	Identific	ed Rootcause			Recommendation			
> The printed image on the item contaminates the other item because the position of glued items in the conveyor is not slanting since the roller was removed					~No removing of roller on the machine			
		III COPPE	OTIVE 4.00			dout by OA la shows		

	Checked by	Date	Implen	nented?	Remarks
1st Verification of Action	A. Vergara	20 08 14	[√Yes	[] No	c A. is implemented
2nd Verification of Action			[]Yes	[] No	
3rd Verification of Action			[]Yes	[] No	
Effectiveness of Action	A. Vergava	20 10 07	[/] Yes	[]No	C.A. is effective

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE									
Status Remarks.	Approved by:	Process Owner Acknowledgment: (Receiving Section)							
QUALITY ASSURANCE DEPAR	(INEN/ Wan	ALL I							
Still O	GA upervisor QA Ast Manager	Line Leader Department Head							
Re-Is ue IRF		Date: 21 01 04 Date: 21 0 04							
DATE AND Ama									

INVESTIGATION REPORT FOR SCRATCHES OF SANYO DENKI 00939007-01 CORRUGATED CARTON

W1- Item did not inclined after feeding in Semi-Auto gluing.

DIRECT CAUSE PROCESS/MATERIAL

W2- Operator removed the roller why the item get flat in the belt.

W3- Item flat in belt and because of the jogger why the back side of box got scratches by belt.



Operator remove this roller because according to them when they process small box like EPSON 0864 the items did not push continuously by belt because it was inclined.



INDIRECT CAUSE PROCESS/MATERIAL

W1- Semi auto gluing operator not immediate notice the scratches because the occurrence is randomly, and when they notice it they immediate inform the Production Leader in-charge and transfer the process in manual gluing for the meantime.

CORRECTIVE ACTION

Back the roller of Semi-Auto Gluing								
PIC:	PRODUCTION	TARGET DATE:	200806					

Re-orient the semi-auto gluing operator regarding Abnormality Rule and do not remove anything fixed part of machine without approval of Leaders.

PIC: PRODUCTION TARGET DATE: 200810

PREPARED BY:

GERAVO DE GUZMAN PROD ASST. SUPERVISOR APPROVED BY:

WEENA V. APALLA SR. SUPERVISOR