K	No. 5 Ring Ros	d LISP II, Brgy. L (049) 545-7166 to	E PHILIPPINE INC. a Mesa, Calamba City, Laguna o 69	INVESTIGATION REPORT FORM (IRF)  Inhouse Detection					
11.00	MARKATAN MARKATAN						20 08 27		
Custom		SANYO DENK		Attenti		Mr. Gerald De			
Item Co	ode	00918237-01		Depar	tment	PRODUCTION			
Item De	escription	PACKAGE		Date o	f Detection	20 08 24			
Job Ord	der Number	WO-DRS-20-N	N-1050-203	Sectio	n Detected	QA - IN LINE			
	ILLU	JSTRATION O	F THE PROBLEM		Major		Minor		
DOM: NO.	MASSES STATES AND SECTIONS	2000 DOG		L	ot Quantity (pcs.)	Reject Qua	ntity (pcs.)	Reject Percentage	
		1 !			1,039	26	5	25.51%	
			NEGOVNAS SANÃO DENKI	Nature of Defect:  CLOSE GAP					
				Requi	rement:				
	山洋電気	(株式会社 data truy the system		Gap measurement is 6mm ±3mm					
	00918237	7     1		Actual					
,						No gap o	n the slot		
	NO. OF OCCURRE	NCF	DISPOSITION		AREA OF OCCI	JRRENCE / ORK	SIN	CONTENT	
	First		Hold		Slotter	Gluing		Material	
<b>建設器</b>			Special Acceptance		EQOS	Vertica		Dimension	
	Recurrence					Others		Appearance	
	No.:		For Rework		Diecut	Uners		Edition 1	
With the second	Date:		Reject / Disposal		Detaching		-	Process / Method Received by	
	Issued by		Checked by		Approved b	У		(Receiving Section)	
	Adrian Vergara QA-IE Staff	a	Ms. Noemi Cepeda QA Supervisor		Mr. Rexel Alm QA Asst. Mana			Gerald De Guzman lead/ Supervisor	
			I. INVESTIGAT	TION / A	NALYSIS				
	DIRECT CAUSE: (Ar	nalyze the reaso	on of occurrence, why it happened?)		INDIRECT CAUSE	: (Analyze the re	ason of occurre	ence, why it leaked?)	
	Why 1:			Why 1:					
ining	Why 2:			Why 2:					
System / Training	Why 3:			Why 3:					
stem	Why 4:			Why 4:					
Sy	Why 5:			Why 5:					
				Why 1:					
sbL	Why 1:			Why 2:					
Design / Toolings	Why 2:								
gu /	Why 3:			Why 3:					
Desi	Why 4:			Why 4:					
	Why 5:			Why 5:					
<u>m</u>	Why 1:			Why 1:					
Process / Material	Why 2:			Why 2:					
SS / N	Why 3:			Why 3:					
roces	Why 4:			Why 4:					
Δ.	Why 5:			Why 5:					

## KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69

## INVESTIGATION REPORT FORM (IRF)

Fax	No. (049) 545-6302	Antonio Vanno Antonio Antonio	Winds a second view	(otenities) in the property of	THE RESERVE OF THE PERSON OF T	MATERIAL STATES		THE WAY OF THE PARTY OF THE PARTY OF THE	TO STATE OF THE ST
				FINAL CON	CLUSION				7974 7974 (1986)
	OCCURRE	NCE ROOTCAUSE				Ol	JTFLOW ROOTCA	USE	
IMMEDIATE A	ACTION: (Action to be de	one to contain/ temporary	y correct the pro	oblem found)	CORREC	TIVE ACTION: (Actio	ns to be done to ensure	e that the problem will	I not happen again)
A. Sorting Result						Actions to be don	e to eliminate recui	rence	Who / When
	Location	Total Stock	NG	Total Good					
RM					System				
WIP					System				
FG									
3. Orientation									
Date		Time			Design /				
Title			11		Tools				
dees									
C. Reworking						1 = = = = = = = = = = = = = = = = = = =			
Rework Quantity					D				
Total Good					Process	N = - 1			
Rework Percentag	ge (Good)	1							
II. QA ROO	TCAUSE VERIFICAT	TION (To be filled o	ut by QA In	-charge)	Date Conduc	cted:	PIC:		
	Identif	ied Rootcause					Recommendation	n	
	44.	III. CORREC	CTIVE ACTI			led out by QA In-c			£ 4 (4)
	C	Checked by	Date	Implem	nented?		Rem	arks	
1st Verification of	of Action			[]Yes	[ ] No				
2nd Verification	of Action			[]Yes	[ ] No				
3rd Verification of	of Action	F F		[ ]Yes	[ ] No				
Effectiveness o	f Action			[ ]Yes	[ ] No			z _ s	-
				1		25 520 - 338 - 35 45			0.00
Note: If no same deliveries or 3rd	e defects / problems of verification of action	occurs for 5 consecu still not yet impleme	tive deliverie nted, Invest	es, corrective act igation Report sh	ion is conside all be re-issu	ered effective / close ed to the affected d	ed. If the same prote epartment to provid	olem occurs within le new improvem	n 5 consecutive ent action.
				IV. CLC					
	ALITY ACCUE	ANCE DEPAR	TMENIT		ved by:		rocess Owner Ack	nowledameht: /R	eceiving Section)
Closed -		MINUE DEPAR	VINCIAI	Appro	veu by.		A A	omeagment. (IX	John S Coulon)
Closed G	ited by supp	olen	QA	upervisor	QAÁş	MANAGER MANAGER	Line Leader		partment Head
Re-Issue			Pate	510)11	Date: AX	0    \   Da	te: 21 01 11	Date: 2	1 01 01
DATE AN SIGNATUI		2/01	09						

fox

KANE

## MANEPACKAGE PHILIPPINE, INC.

30 No. : JO No. : ISSUED BY : JM DDATE ISSUED :

CUSTOMER

Sales Order #DRS-20-M-01050 WO-DRS-20-M-01050-203 Engleberth Dario 28-JULY-2020

SANYO DENKI PHILS INC

NETSUME da transper to FG



Light Industry Science Park II. National Highway, Calambe, 4027 Laguna Tel:(049) 545 7100/67 Fax(049)544-0010

Item Description: Quantity:

00918237-01 PACKAGE

1200 Piece

29-JULY-2020

Memo: BK Code: Blades:

E35

FG 157

00918237-01

Delivery Date: **Material Description** 

567X1699 CBF TX200 W/ CREASING LINE 0

Qty To Be Used No. of Cuts Actual **Cut Size Qty Used** 2/1 0pcs 1215

DR No. 818 2922

Supplier Batch No.

Issued By ELME

PROCESS Finished Date 1		shed Time	GOOD QTY Trial Ru		un REJECT QTY In-house Supplier		OPERATOR	Remarks
LEGOS Pousoto	8-8		12:15	2			PENRI	No.
2.SEMI AUTO GLUING	8/06	,	820	2			Jayson / JEFF	
B.LOT NUMBERING	8/00		poo			屯	HM/ FOROM	
4.SCREENING	8/		70			783	JEXTER	
5.QA BUNDLE	10Ce				ngo qobaashii aayya aa aa aa ka ka ka		JEXTER EDNON	
	8/6	)	8.1	REJE	CTION HISTORY	. 18	7-210	
1. 2. 3. 4. 5.					A CONTRACTOR OF THE PARTY OF TH	1		

NOTES

)						1
1.	820	transferred	to	BA	-ther	Bhe
2.		•				1
-					4	61

4.


PR-001-F07 REV.00

JO Received By(WHSE):

Signature over printed name/Date/Time

JO Returned to(QA):

Signature over printed name/Date/Time



SANYO DENKI PI	HILS. INC.	
00918237-01	dy QUANTITY  10 pcs.	
Item Description PACKAGE	Supplier's QC PASSED	
Lot No. / Ref. No.	INSPECTION RoHS OK	
200806 - 01050-203 KANEPACKAGE PHII	QA-CG568 LIPPINES INC.	