KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna					INVESTIGATION REPORT FORM (IRF)				
		(049) 545-7166 t			Inhouse Detection Customer Claim				
			N	Contro	ol No.: 316	Date Issued: 20 10 29			
Custo	mer	SANYO DENI	(I	Attention To Mr. Gerald De Guzman					
Item C	ode	00939007-01		Depar	Department PRODUCTION				
Item D	escription	CORRUGATE	D CARTON	Date o	of Detection	20 10 24			
Job O	rder Number	WO-SO-20-M-	-01567-1	Sectio	n Detected	QA - SCREENING			
	ILLI	USTRATION O	F THE PROBLEM		Major	Minor			
go sette			7	L	ot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage		
					500	43	8.60%		
1	/ July			Nature	e of Defect:				
					POOR PRINT				
				Requirement:					
				Solid image should be completely filled by ink					
				Actual:					
		,		The solid images have line mark from anilox					
	NO. OF OCCURRE	NCE	DISPOSITION		AREA OF OCCU	RRENCE / ORIGIN	CONTENT		
	First		Hold		Slotter	Gluing	Material Material		
	Recurrence		Special Acceptance		EQOS	Vertical	Dimension		
, P	No.:	For Rework		Diecut	Others:	Appearance			
	Date:		Reject / Disposal		Detaching	<u> </u>	Process / Method		
	Issued by Checked by				Approved by		Received by (Receiving Section)		
Ó	Adrian Vergara Ms. Noemi Cepeda QA-IE Staff QA Supervisor				Mr. Rever Almatio QA Asst. Manager Mr. Gerard De Guzman Head/ Supervisor				
	DIRECT CAUSE: (Ana	alvze the reaso	n of occurrence, why it happened?)	ON / AI		(Analyze the reason of occurr	ance why it leaked?)		
	Why 1:	aryze the reason	ir or occurrence, why it happened?)	Why 1:	INDINEET GAUGE.	(Analyze the reason of occur	erice, wity it leakeur)		
guir	Why 2:			Why 2:					
System / Training	Why 3:	N/A			Why 3: Why 4:				
	Why 4:								
	Why 5:			Why 5:					
	Vhy 1:			Why 1:					
Design / Toolings	Why 2:	N/A							
	Why 3:					N/A			
	Why 4:					MA	.87		
	Why 5:						- *		
	Why 1:			Why 5: Why 1:	-	un en			
Process / Material	Why 2:	1		Why 2:					
		LS. SEE ATTACHED		Why 3:	DIC	CE ATT			
	Why 4:	<i></i>	C MITTORICD	Why 4:	rL>.	SEE ATTAC	HED		
				Why 5:					

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

	Fax No. (049) 54	5-6302								
() to "					CLUSION		7			
	00	COURRENCE	ROOTCAUSE		1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1	OUTFLOW ROOTCAUSE				
		Er Welchele Con	S THE M WESS ON TO		- PANDOM OCCURRENCE AND IT IS NEWORKABLE.					
IMMEDIA	TE ACTION: (Ac	tion to be done t	o contain/ temporary	correct the prol	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
A. Sorting Resu	ult		1		1	Actions to be done to eliminate recurrence Who / When				
	Loca	tion	Total Stock	NG	Total Good					
RM	N/A	-				System	N/4			
WIP	N/A					, -,	N/A			
FG	N/A						* a * *			
B. Orientation										
Date	NIA		Time N/A			Design /	6) /4			
Title			N/A			Tools	N/A			
endees	- Y		NIA							
C. Reworking	and the second second									
Rework Quan	itity	NIA				D	Pic co			
Total Good	The Head	NIA			Process	PLS. SEE ATTAGLED				
Rework Percentage (Good)			N/A							
II. QA F	ROOTCAUSE V	ERIFICATIO	N (To be filled o	ut by QA In-	Date Conducted: 101104 PIC: A-Vergara					
Wilderson H. Swat erenanti-acc		Identified	Rootcause		Recommendation					
The impre not enoug	ession ap In to fill-in	Plied on the soli	the corru d image o	gated by the iter	Add printing impression in the setup: Ink Nip of 6.5 Print pull Nip of 2.8~3.0					

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)								
	Checked by	Date	Implem	nented?	Remarks			
1st Verification of Action	A. Vergara	20 11 04	[/] Yes	[] No	Recommendation is implemented			
2nd Verification of Action			[]Yes	[] No				
3rd Verification of Action			[]Yes	[] No				
Effectiveness of Action	A. Vergara	20 12 22	[]Yes	[] No	Recommendation is effective			

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE										
DAUDEN	QUALITY ASSURANCE DEPARTMENT			Appro	oved by:	Process Owner Acknowledgment: (Receiving Section)				
Closed Still Open			And and		A Supervisor	QA Asst Manager	Line Leader	Department Head		
Re-Isque IR				Date	216414	Date: MOULU	Date: 210414	Date: 210414		
DATE AND	1	222	101 1	41 24	17	V				

INVESTIGATION REPORT FOR POOR PRINT OF SANYO DENKI 009390007-01 CORRUGATED CARTON

DIRECT CAUSE PROCESS/MATERIAL

 ${f W1}$ - Operator already noticed the random occurrence of poor print, he tried to adjust but the outcome is worst than before. So he stick on the original setup to avoid more rejection.

W2 - Possible factor is the material it might be the thickness or the texture but we can't 100% be sure.

INDIRECT CAUSE (OUTFLOW)

W1 - Even Eqos main operator notice some poor print he did not totally change the printing setup, because occurrence are random and it is reworkable.

PRODUCTION CORRECTIVE ACTION

Will investigate and observe closely next running to find possible root cause to give definite countermeasure.

PIC: PRODUCTION TARGET DATE: NEXT RUNNING (201104)

PREPARED BY:

GERALD DE GUZMAN PROD ASST. SUPERVISOR APPROVED BY:

WEENA V. APALLA SR. SUPERVISOR