

INVESTIGATION REPORT FOR BURSTING SB (515411300-LOUVRE MDX MINI ETD)	
DIRECT CAUSE METHOD / PROCESS	W1: Still under investigation
INDIRECT CAUSE METHOD / PROCESS	

PRODUCTION ACTION PLAN
CORRECTIVE ACTION Monitoring of 1 hour curing time.
PREVENTIVE ACTION: Strictly follow the 1 time running in sheetboard items.

Prepared by: PRODUCTION IE TEAM Sir Marco Pesa	Reviewed by: Noemi Cepeda PRODUCTION SUPERVISOR
---	---

