) · · ·
KANEPACKAGE PHILIPPINE INC.

Control No.

KANEPACKAGE PHILIPPINE INC.		ABNORMA	ALITY REPOR	RT	AR-02-000240
I. Item Information					
Item Code	5159122-00		Customer	EPSON IJP	
Item Description	LOUVRE 2 MJX ICB FOR	EAL	Delivery Date	FEBRUARY 08, 2	2022
Detection (Section / Area)	EPSON IJP		Job Order Number	12852	
Inspection Date	220207 N/S		External Provider	KPLIMA	
Affected Quantity	48/197 Rejec	t % : 24.37%	Date Received	FEBRUARY 07, 2	1022
Problem Description	MIXED MODEL		Delivery Receipt Number	220203 NS (Date	
I. Visual Reference (Defect	Illustration)		2 and y redespertament	220200 NO (Date	r roudced)
			5159112-0 5159122-0		
II. Documented Information Related Doc. Info.	Review (To be filled out	by QA Line leader)			
Procedure Manual :	Control Number	Requirement:			
Technical Drawing :				Li .	
Work Instruction :		Actual:			
Job Order :			ř.		
Reports :	6	Conclusion and			Applicable
Defect Limit :		Recommendation:			Not Applicable
	filled out by ME Day of				
V. Initial Disposition (To be					
Good Cond	ditional (Please indicate de		kload	lease indicate deta	
			Person In Cha	arge Targ	et Date Signature
			Sorting		
		For	Rework		
Remarks:					
Detected by	Checked by	Initial Approved	by (If Needed)	pproved by	Noted by
QA Inspector	QA Line Leader	ME C	on the s	Lewolog	
		ME Sup		A Supervisor	QA Head
mportant: Backloading Polic Provider Rejects)		Evaluation	Approved by		Final Disposition
rovider Rejects) Rejection rate that is more than uantity shall be approved by T efore backloading.	n 80% of the total 🗀	80% No Need 80% Need	Top Management		ckload cept

KANEPAC	KAGE PH	LIPPINE	INC.	Æ	BNORMA	ALITY	RE	PORT			
VI. Item Information	on										
Item Code		5159122-	-00		Customer	E	PSON I	JP			
Item Description		LOUVRE	2 MJX ICE	FOR EAL	Delivery Date	F	EBRUA	ARY 08, 2022			
Detection (Section	on / Area)	EPSON I	JP		Job Order Numb	per 1	2852				
Purchase Order	Number	N/A			External Provide	er K	PLIMA				
Delivery Receipt	Number	220203 N	IS (Date Pr	roduced)	Item Date Recei	ved F	EBRUA				
VII. Sorting Details Instructions	s/					•					
VIII. Sorting Detail	ls/ Instruc	tions									
	Sortin	g Time	No. of								
Sorting Date	Start	End	Man- power	Lot Number	Sorted Quantity	Reject Q	uantity	Defect Name	Sorted by		
Sorting Result R&R Verification		I Sorting H	lours	Total No. of Manpower	Total Sorted Quantity	Total Reject	Quantity	Total Good Quantity	Rejection Rate (%		
X. Reworking Det If Reworkable)	ails										
K. Reworking Res	ult										
Powerking Data	Rework	ing Time	No. of								
Reworking Date	Start	End	Man- power	Lot Number	Reworked Quantity	Good Qu	antity	Reject Quantity	Rejection Rate (%		
Prepa	red by			Checked by	Appro	ved by		Note	ed by		
RNR	Staff	E (VAL)		QA Line Leader	QA Su	pervisor		QA	Head		

Note: All details must be filled out completely.
Submit this form to Line Leader immediately after accomplishment.

QA-003-F13 REV.03

1	No. 5 Ring Road	d LISP II, Brgy. L	SE PHILIPPINE INC.	II		TION RE	PORT	FORM (IRF)	
	Telephone No. Fax No. (049) 5	(049) 545-7166 to 545-6302	o 69	Inhouse Detection Customer Claim					
Custom	nor	EPSON IJP		in the second	ol No.: IRF-00240			FEBRUARY 09, 2022	
Item Co		5159122-00		1124,36	Attention To SUZETTE DIMAYUGA/ JOEY MARQUEZ Department KPLIMA WHSE/ KPLIMA QA				
	em Description LOUVRE 2 MJX ICB FOR EAL				of Detection	FEBRUARY 08,			
	Job Order Number 12852				n Detected	EPSON IJP	2022		
ILLUSTRATION OF THE PROBLEM						EPSON IJP	Minor		
(Market)	ILLO	Jankarion of	F THE PROBLEM		Major ot Quantity (pcs.)	Deignt Over	Minor	Delect Descentes	
EN	4				197	Reject Quan	iity (pcs.)	Reject Percentage 24.37%	
A WALL			5159112-00 Reject	Natur	e of Defect:	MIXED M	ODEL		
			5159122-00 Good	Requi	rement:				
					EPSON REQUIRE	MENT : 5159122-0	00 LOUVRE 2	MJX EAL -120PCS	
				Actua	i:				
				5159122-00 LOUVRE 2 MJX EAL -72PCS					
	NO. OF OCCURRE	NCE	DISPOSITION						
	First		Hold	П					
	Recurrence		Special Acceptance						
	No.:		For Rework						
	Date:		Reject / Disposal			Others.	8		
	Issued by		Checked by			v		Received by	
								(Receiving Section)	
M.	QA-IE Staff		QA Suparvisor		QA Asst. Mana	ager	He	ead/ Supervisor	
			I. INVESTIGAT	ION / A	NALYSIS				
	DIRECT CAUSE: (Ana	alyze the reaso	on of occurrence, why it happened?)		INDIRECT CAUSE	: (Analyze the reas	son of occurre	ence, why it leaked?)	
D	Why 1:			Why 1:					
ainin	Why 2:			Why 2:					
m/T	Why 3:			Why 3:					
System / Training	Why 4:			Why 4					
	Why 5:			Why 5					
ω .	Why 1:			Why 1			(6)		
oling	Why 2:			Why 2					
Design / Toolings	Why 3:		*	Why 3	5159122-00 LOUVRE 2 MJX EAL -72PCS 5159112-00 LOUVRE 2 MDX EPIL -48PCS AREA OF OCCURRENCE / ORIGIN Gluing Material EQOS Vertical Dimension Diecut Others: Appearance Process / Method Approved by Received by (Receiving Section) Approved by Received by (Receiving Section) I/ANALYSIS INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?) thy 1: thy 2: thy 3: thy 4: thy 5: thy 1: thy 2: thy 3:				
Desig	Why 4:			Why 4					
	Why 5:			Why 5					
<u>a</u>	when month	i bassi lla	sed the the issued excess item advance all excess item advance all excess item advanced	Why 1					
/lateri	Why 2: punning on 5	Semi Auto Gil	ming.	Why 2					
Process / Material	Why 3: who comparing	on marking	wing. 2003 (418pcs.) on 5159111200 (70pcs.) The actual issued excess years The 2 and altached unoung Lot Label. Label based on the attached FC Ta 2003),	Why 3					
Proce	Why 4: BA inspector	create Lot	Label based on the attached FC To	Why 4					
-	Why 5:		20 E	Why 5					

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

				FINAL CON	CLUSION			
	00	CCURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE	
IMMEDIAT	E ACTION: (Ad	tion to be done to contain/ tempora	ry correct the pr	oblem found)	CORRECTIV	VE ACTION: (A	ctions to be done to ensure that the	problem will not happen again)
A. Sorting Resu	lt					Actions to be d	lone to eliminate recurrence	Who / When
Wilder Control of the Control	Loca	tion Total Stock	NG	Total Good				
RM					Custom			
WIP					System			
FG								
B. Orientation								
Date		Time			Design /			
Title					CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again) Actions to be done to eliminate recurrence Who / When System Design / Tools Process Date Conducted:			
Attendees						13		
C. Reworking								
Rework Quant	ity				Process			
Total Good								
Rework Perce	ntage (Good)							
II. QA R	OOTCAUSE V	ERIFICATION (To be filled	out by QA In	-charge)	Date Conducte	ed:	PIC:	
		Identified Rootcause					Recommendation	
					,			
		HARRIS AND MARKET STATE OF	ECTIVE ACT			d out by QA Ir		
		Checked by	Date	Implem	ented?		Remarks	
1st Verification	on of Action			[]Yes	[] No			
2nd Verificati	on of Action			[]Yes	[] No			
3rd Verification	on of Action			[]Yes	[] No			
Effectivenes	ss of Action			[]Yes	[] No			
	() S () S			IV. CLC	SURE			
Status:		Remarks:		Approv	ved by:		Process Owner Acknowled	gment: (Receiving Section)
Closed								
Still Open			QA S	Supervisor	QA Asst.	Manager	Line Leader	Department Head
Re-Issue IRF			Date:		Date:		Date:	



INLINE TRANSMITAL FORM

DATE	CUSTOMER ,	JO #	ITEM DESCRIPTION	ITEM CODE	QTY.	RECEIVED BY
2/3/2022	EPSON	12681	Louvre 2 LABX ASIA	516297800	E- 68	R-13 &
"FEF 79.		12031			44 120	
					120 120 120	3
					12012012	-
					120120120	1
					170 150	
						100
					1484 T- (1497)	
		-			T- (497)	
		12,700	Lource 2 Myx EAI	515912200		
					120	-
					12012012	0
					12012012	5
	2"				20 15	
					975	16
			,		T- (975)	
	70					
		12682	LOUYER 2 MIX EAT	510912200		
					115 120	12-13
	**************************************				12012013	20
					120(20)	20
		81			120 1200	20 BOVE
					120 1201	20)
a si					120120	12 3
					1987	26
					T- (2000)	(h
						,
						7
		12683	Louvre 2 Mily Forching	515913300	120 82	
					202	
					7- (202)	6
		12702	Lourn 2 MCX For chi	ing 5 15 913400	12087	_ / ;
		14/02			207	
					T-(207)	(h)
ř		12704	Louvrez Mox china	5[6334900	12012012	0 R-8
					1201207	1
					671	4
				4	T-679	



INLINE TRANSMITAL FORM

DATE	CUSTOMER	JO #	ITEM DESCRIPTION	ITEM CODE	QTY.	RECEIVED BY
2/7/2022	EPSON	00-012851	house 2 mak Indoneyor	515011100	(345) 84	1
			10104: (183)	45.	120 120 120	
			1		34	25)
				ϵ	+ 448	777
	. \	40-12852	house 2 male spl	675a11200	(42) 48	
1200		15	powle (03)	BROKEN	120 20	ku)//
				ब्रानः -	109	
		10-12864	loung 2 mux Asia	5150110000	150 150.150	
			TOME SIGNS		09 09 09	
			Will was		00 00 00	1/1
					120 120 120	V-1
					100 100 100	
					०व १५व १०व	
					14	(29)
						tea)
		10-12865	lover min Jadonena	514297900	(108) 12	- \
		V	PORTE (LOU)	O 102013 O 100	120 120 120	
			TOWN WAY		120 120 120	11
					120 20 120	
					120 120 120	
					120 24	(27)
					1599	ET) / [
		do-128w	lovur 2 mys enl	575/112200	1300 120 120	1/8
-		QV I≈av	Jobal F (118,)	0.31,2200	120 120 120	
			10/41/10)		190 190 190	1
*					201	(89)
					1109	JK. J
					1100	
		Reg.	515912200 -	2)		*
		Actual	: 515911200 -(4			
		40,00	2 3.30111200 40			
				-		
		1				
		-				
	A	-				
		-				