KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302					INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: IRF-05-0001 Date Issued: 4-May-22						
Customer				Attentio		NOEMI CEPEDA					
Item Code 516298200						KPLIMA-PRODUCTION					
Item Description	on LC	OUVRE 2 MC	X ASIA	Date of Detection		2-May-22					
Job Order Number 15474		474	*	Section Detected		INLINE QA					
	ILLUST	RATION OF	THE PROBLEM	Major			Minor				
3333 O			OBJECT IN		t Quantity (pcs.) 1,709 of Defect:	Reject Qual		Reject Percentage 5.38%			
EPSON Enter 1270 EPSON EPSON ENTER 1270 EPSON ENTER 1270 EPSON ENTER 1270 EPSON ENTER 1270 EPSON EPSON ENTER 1270 EPSON EP					PEEL OFF						
8			04,500	Requirement:							
	0.000					ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF PEEL OFF					
Botton SEE Fred	n OTTE Bauch	Marcin AMS		Actual:	Actual:						
					PEEL OFF OCCURRED IN CLASS A PRINTER IMAGE; DUE TO SPLASHING						
NO. OF OCCURRENCE			DISPOSITION	AREA OF OCCURRENCE / ORIGIN			GIN	CONTENT			
First			Hold	Slotter Gluing Ma				Material			
Recu	rrence		Special Acceptance		EQOS Vertical			Dimension			
No.:			For Rework		Diecut Others:			Appearance			
Date:			Reject / Disposal		Detaching			Process / Method			
Issued by			Checked by		Approved b	у		Received by			
d. Chenie Anne Arevalo QA-1E Staff		_l lo	G. Masino OA Supervisor			QA Asst. Manager		Head/Supervisor			
			I. INVESTIGAT	TION / AN							
DIRE	CT CAUSE: (Analy	ze the reaso	n of occurrence, why it happened?)	INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)							
System / Training / Myh 7	:			Why 1: Why 2:							
Why 3				Why 3:			٠,				
100				Why 4:							
Why 5	Why 5:			Why 5:							
Why 1	:			Why 1:							
Sesion V Tooling Why 2	Why 2:				Why 2:						
Why 3	Why 3:				Why 3:						
Osio Why 4	Why 4:			Why 4:							
and the second	Why 5:			Why 5:							
Why	1:			Why 1:							
My 3: My 4: My 4:					Why 2:						
Why:	3:			Why 3:							
Why	4:			Why 4:							
Δ. Northy	5.			Why 5:							

KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

				FINAL CON	CLUSION					
	OCCURREN	CE ROOTCAUSE			OUTFLOW ROOTCAUSE					
IMMEDIATE ACTIO	ne to contain/ temporary	correct the pro	oblem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)						
A. Sorting Result				Actions to be done to eliminate recurrence Who / When						
2.400.000.000	Location	Total Stock	NG	Total Good						
RM					System					
WIP					System					
FG										
B. Orientation										
Date		Time		De						
Title					Tools					
Attendees										
C. Reworking										
Rework Quantity					Process					
Total Good					1 100033					
Rework Percentage (Go	ood)									
II. QA ROOTCAU	SE VERIFICAT	ION (To be filled o	out by QA In	-charge)	Date Conducte	ed:	PIC:			
	Identifi	ed Rootcause			Recommendation					
		III CORRE	CTIVE ACT	ON VERIFICATI	ON (To be fille	ed out by QA l	n-charge)			
		hecked by	Date		nented?	a out by a rt	Remarks			
1st Verification of Acti		Hebred by	Date	[] Yes	[] No					
2nd Verification of Action			[]Yes []No							
3rd Verification of Action			[]Yes		[] No					
Effectiveness of Action		,		[] Yes	[] No					
Note: If no same defe consecutive deliverie improvement action.	ects / problems es or 3rd verifice	occurs for 5 consec ation of action still n	cutive delive ot yet imple	eries, corrective a mented, Investig	action is consid ation Report si	lered effective hall be re-issue	od to the affected department	occurs within 5 to provide new		
				IV. CLC	OSURE					
Status: Remarks:		Appro		ved by:		Process Owner Acknowledgment: (Receiving Sec				
Closed Still Open			QA S	Supervisor	QA Asst	. Manager	Line Leader	Department Head		
Re-Issue IRF			Date:		Date:		Date:	Date:		
L										