K	No. 5 Ring Roa	ad LISP II, Brgy. L (049) 545-7166 to	SE PHILIPPINE INC. a Mesa, Calamba City, Laguna o 69	INVESTIGATION REPORT FORM (IRF) Inhouse Detection				
Custon		EPPI IJP		The second secon				
				Attention To NOEMI CEPEDA				
Item Co		RX1-4249		Department KPLIMA-PRODUCTION				
	escription	CARTON BOX		Date of Detection 21-May-22				
Job Ord	der Number	16302		Section Detected DIECUT QA				
	ILLU	USTRATION O	F THE PROBLEM	Major				
8014249				Lot Quantity (pcs.) Reject Quantity (pcs.) Reject Percentage 3.62% Nature of Defect: BURSTING Requirement: ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF BURSTING Actual:				
				BURSTING OCCURRED ON THE HÄNDHOLE				
	NO. OF OCCURRE	NCE	DISPOSITION	AREA OF OCCURRENCE / ORIGIN CONTENT				
First Hold Special Acceptance				Slotter	Gluing	Material		
				EQOS	Vertical	Dimension		
No.: For Rework Date: Reject / Disposal			Diecut	Others:	Appearance			
			Detaching		Process / Method			
	Issued by		Checked by	Approved by Received by (Receiveng Section)				
	Cherte Anne Are QA-IE Staff	nalo	A Supervisor	QA Asst. Manager Head/ Supervisor				
	DIDÉCT CALISE (A	alusa tha sassa		TION / ANALYSIS				
		nalyze the reaso	on of occurrence, why it happened?)		SE: (Analyze the reason of occur	rence, why it leaked?)		
System / Tra	Why 1: Why 2: Why 3: Why 4: Why 5:			Why 1: Why 2: Why 3: Why 4: Why 5:				
Design / Toolings	Why 1: Why 2: Why 3: Why 4: Why 5:			Why 1: Why 2: Why 3: Why 4: Why 5:				
Process / Material	Why 1: Why 2: Why 3: Why 4: Why 5:			Why 1: Why 2: Why 3: Why 4: Why 5:				



KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy, La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

	Fax No. (049) 54	5-6302	14 4-7		- 1		SAN L	25/19/4		P. L.	
					FINAL CON	ICLUSION					
OCCURRENCE ROOTCAUSE							OUTFLOW ROOTCAUSE				
IMMEDIA	TE ACTION: (A	ction to be done to	o contain/ tempora	ry correct the pro	blem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
A. Sorting Resu						Actions to be done to eliminate recurrence Who / Wh					
Loca		tion	Total Stock	NG	Total Good				Ne		
RM			12 3 3						《 集页	12.1	
WIP .	P		1/22	Cold Wall		System					
FG											
3. Orientation		7799									
Date		Time				Design / Tools					
Title	X 3 3 2 4										
Attendees										1	
C. Reworking		1 1 1 1 1 1 1 1								3.7.0	
Rework Quant	ity			Yes		Defense					
Total Good						Process		•			
Rework Percei	ntage (Good)									1.0	
II. QA R	OOTCAUSE V	ERIFICATION	(To be filled o	out by QA In-	charge)	Date Conduct	ed:	PIC:			
		Identified F	Rootcause			to Line		Recommendation			
			III. CORRE	ECTIVE ACTIO	ON VERIFICATI	ON (To be fill	ed out by QA I	n-charge)			
		Check	ked by	Date		nented?		Remarks			
1st Verification of Action				[]Yes		[] No					
2nd Verification of Action				[]Yes		[,] No					
3rd Verification of Action				[]Yes		[]No					
Effectiveness of Action			<i>I</i>	[]Yes		[] No					
Note: If no sa deliveries or	ame defects / p 3rd verification	roblems occur of action still i	rs for 5 consec not yet impleme	utive deliverie ented, Investig	s, corrective ac gation Report st	tion is consider hall be re-issue	red effective / cl	osed. If the same problem of d department to provide new	ccurs within 5 o v improvement	consecutive action.	
					IV. CLC	DSURE					
Status:	tatus: Remark		Remarks:		Appro			Process Owner Acknowledgment: (Receiving Section			
Closed		11/19			7 54		13				
Still Open	Still Open Re-Issue IRF			QA Supervisor		QA Asst. Manager		Line Leader	Departr	ment Head	
Re-Issue IRF			The second		Date:			Date:	Date:	7 A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	