K	No. 5 Ring Roa Telephone No.	d LISP II, Brgy. La (049) 545-7166 to	E PHILIPPINE INC. a Mesa, Calamba City, Laguna 69	IN	VESTIGA Inhouse Detection		RT FORM (IRF) Customer Claim			
				Control	No.: IRF-06-0001	ued: 07-Jun-22				
Custome	Customer EPPI IJP				on To	NOEMI CEPEDA				
Item Code 515911300 PANEL B					ment	N				
Item Description LOUVRE 2 MDX EPIL					Date of Detection 07-Jun-22					
Job Order Number 16926					Section Detected INPROCESS QA					
	ILLU	JSTRATION OF	THE PROBLEM		Major	Minor				
		-			Lot Quantity (pcs.) Reject Quantity (pcs.) Reject Percent 400 278 69.50% Nature of Defect:					
RECENT DEPOSITS PROVIDED TO THE PROPERTY OF TH					GLUE STAIN					
			1	Requirement:						
					ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF GLUE STAIN					
	Ed http://www.news.com/			Actual	Actual: GLUE STAIN OCCURRED ON THE PANELS					
	NO. OF OCCURRE	ENCE	DISPOSITION	AREA OF OCCURRENCE / ORIGIN CONTENT						
	First		Hold		Slotter	Gluing Material				
First Recurrence No.: Date:			Special Acceptance		EQOS	Vertical	Dimension			
			For Rework	Diecut Others: Appearance						
				Detaching Process / N						
	Tax No. (049) 545-6302 Itomer EPPI IJP Code 515911300 PANE Description LOUVRE 2 MDX ILLUSTRATION OF TO NO. OF OCCURRENCE First Recurrence No.: Date: Issued by C. Arevalo QA-IE Staff DIRECT CAUSE: (Analyze the reason of Why 1:		Checked by	Approved by		y	Received by (Receiving Section)			
	•		G. Magsino QA Supervisor		QA Asst. Man	ager	N. Heleda Head/ Supervisor			
			I. INVESTIGAT	ION / A	NALYSIS					
	DIRECT CAUSE: (A	nalyze the reaso	on of occurrence, why it happened?)		INDIRECT CAUSE	E: (Analyze the reason of	occurrence, why it leaked?)			
System / Training	Why 2: Why 3: Why 4:				Why 1: Why 2: Why 3: Why 4:					
					Why 5:					
Sp					Why 1:					
oolin .				Why 2:						
T/ut	Why 3:				Why 3:					
Desiç	Why 4:				Why 4:					
	Why 5:			Why 5:						
<u>@</u>	Why 1:			Why 1:	Why 1:					
lateri	Why 2:			Why 2:	Why 2:					
SS / N	Why 3:									
roce	Why 4:			Why 4:						
۵.	Why 5:			Why 5:						

R

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69

INVESTIGATION REPORT FORM (IRF)

Fax	No. (049) 545-6302								
				FINAL CON	CLUSION				1
	OCCURRE	NCE ROOTCAUSE		OUTFLOW ROOTCAUSE					
IMMEDIATE A	ACTION: (Action to be	done to contain/ temporar	y correct the pr	oblem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)				
. Sorting Result						Actions to be o	one to eliminate recurrence	Who /	Whe
	Location	Total Stock	NG	Total Good					
RM					System				
WIP					Cystem				
FG									
. Orientation									
Date	Time				Design /				
Title					Tools				
Attendees									
. Reworking									
Rework Quantity					Process				
Total Good					Flocess				
Rework Percentag	ge (Good)								
II. QA ROO	TCAUSE VERIFICA	TION (To be filled o	out by QA In	ı-charge)	Date Conduc	ted:	PIC:		
	Ident	ified Rootcause					Recommendation		
		III CORRE	CTIVE ACT	ION VERIFICATI	ON /To be fi	led out by QA I	n.charge)		
		Checked by	Date		nented?	led out by QAT	Remarks		
1st Verification of Action		Official by	Date	[]Yes []No					
2nd Verification of Action			[] Yes [] N						
3rd Verification	of Action			[]Yes	[]No				
Effectiveness of	of Action			[]Yes	[]No				
Note: If no sam deliveries or 3rd	e defects / problems I verification of actio	s occurs for 5 consec n still not yet implem	eutive deliver ented, Inves	tigation Report sh	nall be re-issu	ered effective / c ed to the affecte	osed. If the same problem o d department to provide new	ccurs within 5 consect improvement action.	utive
				IV. CLC		4-14-6			
Status: Remarks:		arks:	Approv		/ed by:		Process Owner Acknowledgment: (Receiving Section		
Closed									
Still Open			QA	Supervisor	QA As	st. Manager	Line Leader	Department He	ead
Re-Issue IRF			Date:		Date:		Date:	Date:	