K	No. 5 Ring Roa	ad LISP II, Brgy. La (049) 545-7166 to	E PHILIPPINE INC. 1 Mesa, Calamba City, Laguna 69	INVESTIGA Inhouse Detection	TION RE		FORM (IRF)	
				Control No.:IRF-01014	ntrol No.:IRF-01014 Date Issued: 220525			
Custome	er	CANON		Attention To	Attention To SIR, DICK RAMOS			
Item Cod	de	FX2-5107-000		Department	Department QA			
Item Des	scription	Z10 OUTER B	ox	Date of Detection	220524			
Job Orde	er Number	22-00095-3		Section Detected KP FPIP				
	ILL	USTRATION OF	THE PROBLEM	Major		Minor		
Canon (angulate Canon				Lot Quantity (pcs.) 18 Nature of Defect:	Reject Qua	91-377-191-18	Reject Percentage 16.67%	
1000		Impanana and and and and and and and and an		MIXED PANEL				
	Terrer Conference	Na .		Requirement:				
Can	Capacian are	SHOULD BE FX2-7107 PANEL A AND B ONLY						
FXS-710G-01H PROSTITIONED POUR STATE OF THE PROSTITION OF THE PR			Actual: MIXED PANEL (7107 PANEL A / 7105 PANEL B)					
	NO. OF OCCURR	ENCE	DISPOSITION	AREA OF OCC	AREA OF OCCURRENCE / ORIGIN CONTENT			
	First		Hold	Slotter	Gluing	9	Material	
	Recurrence		Special Acceptance	EQOS	Vertic	al	Dimension	
	No.:		For Rework	Diecut	Other	s:	Appearance	
Date: Reject / Disposal			Detaching					
	Issued by Checked by			Approved I	Approved by Received by (Receiving Section)		Received by (Receiving Section)	
A A Line leader			QA Asst. Manager Head/ Supervisor					
			I. INVESTIGA	TION / ANALYSIS			THE PROPERTY OF	
	DIRECT CAUSE: (/	Analyze the reas	on of occurrence, why it happened?)	INDIRECT CAUS	E: (Analyze the re	eason of occur	rence, why it leaked?)	
cn cn	Why 1:			Why 1: No detection of mixed	panels. (During 10	0% Inspection).		
System / Training	Why 2:			Why 2: The QA Inspector did not conduct detailed checking on both panels of the items and the carton box did not underwent barcode scanning.				
T/ma	Why 3:	N	/ A	Why 3: During checking, the I panel. He does not chused.	nspector focus only neck the code of eac	on the pokayoke th panel and the	e to ensure that there is no double scanner machine is cannot be	
Syste	Why 4:			Why 4: Proper sequence of in (Note: Proper checking	g and checkpoints t	hat are needed to	as not completely follow. to be is incorporated on that W.I.)	
	Why 5:			Why 5: and waiting for other p	parts of the machine	·		
Design / Toolings	Why 1:			Why 1:				
	Why 2:			Why 2:				
	Why 3:	N	1 / A	Why 3: N / A				
Desiç	Why 4:			Why 4:				
	Why 5:			Why 5:				
-	Why 1: Wrong attachn	ment of panels (Dur	ring gluing).	Why 1: The operator overlook the pokayoke mark indicated on the glue tab.				
/ateriz	Why 2: There were m	ixed FX2-7105 Par	nel B on the FX2-7107 Panel B.	Why 2: Assigned operator did not read the pokayoke to identify that there are mixed / wrong panel on the staired pile.				
Process / Material	Why 3: Line clearance of panels from	e was not fully impl n different code.	emented on the process that resulted to mixing	Why 3: Work Instruction for g	gluing 2-joints cartor	boxes was skip	ped.	
Proce	Why 4:		9	Why 4:				
<u>a</u>	Why 5:			Why 5:				

No.

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

	Fax No. (049) 54	5-6302			211112			
				FINAL CON	CLUSION		OUTELOW POOTON IOC	
OCCURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE			
Line clearance was not completely followed					>Proper sequence checking was not followed >Work Instruction for 2-joints carton boxes was skipped			
IMMEDIA [*]	TE ACTION: (A	ction to be done to contain/ tem	porary correct the pro	blem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)			
A. Sorling Resu					Actions to be done to eliminate recurrence Who / When			
	Loca	tion Total Sto	ck NG	Total Good	TO REAL PROPERTY.			
RM	N A	'A				Orient QA Institems.	nspector for the sequence inspection for CBMP	CBMP 22 05 27
WIP	N.	/ A			System	Usage of barcode scanning machine to ensure that the pane adhere is correct.	the panel 22 06 30	
FG	N	/ A			adnere is corre		J.	
B. Orientation								
Date	. N	/ A Time	N	1/A	Design / Tools	11/2		
Title		N/A				N/A		
Attendees		N/A						
C. Reworking								
Rework Quan	itity	N / A			Process	Strictly follow the Procedure for Line Clearance.		22 05 27
Total Good			N/A		17 8 8000000	Strictly follow the Procedure for Line Clearance. Always check the pokayoke mark indicated on the glue tab	glue tab	
Rework Perce	entage (Good)		N/A					
II. QA F	ROOTCAUSE	/ERIFICATION (To be fil	led out by QA In	-charge)	Date Conducted: PIC:			
		Identified Rootcause			Recommendation			
III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge) Checked by Date Implemented? Remarks								
		Checked by	Date	impier	mented?		Remarks	
1st Verification of Action				[] Yes [
2nd Verification of Action			[] Yes [
3rd Verification of Action			[]Yes []No					
Effectiveness of Action				[]Yes []No				
Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.								
IV. CLOSURE								
Status: Remarks: Approved by: Process Owner Acknowledgment: (Rec					ent: (Receiving Section)			
Closed								
Still Open			QA	QA Supervisor		sst. Manager	Line Leader	Department Head
Re-Issue IRF			-47.1	Date: Date:				
Re-Issue IR	rF .		Date:		Date:		Date: Dai	le:



KANEPACKAGE PHILIPPINE, INC.

ATTENDANCE SHEET

SII	hn	nitte	he	h	,
Ou	211	11166	- u	~	

J. Pamplona

Date:

21 05 27

ACTIVITY

Re-orientation of Sequence checking for CBMP Carton Boxes.

Attendees FIRST NAME DIV. / DEPT. SIGNATURE LAST NAME DAR Y, Marun QA Mark Mag cyanes Marrel Her mogo BA AVADO TAKK JOSEPH 0,6 MARIE MOTTHOW LIBRON HOGEMER Suan QA Jexter Tampoc SERIES Q.A ARTCHE 8 DAD 9 AMOH Acrico MICHAEL RA TERMO 10 Mailan OA 11 ana 12 PLC PYAN PANSINGO QA DA VICHONROE YILLAPANDO 13 Francis Q. 4 14 Alcuran Rose anne clamares 15 M Carro Q.A 16 OP MAINA CANACA Artes 17 AC JAMPICA TOSIPH 18 VILLANUEVA LUTELY 0 \$ 19 Morrin ROOMA QA JERIOX 20 21



KANEPACKAGE PHILIPPINE, INC.

ATTENDANCE SHEET

Submitted by:

J. Comiento

Date:

220527

ACTIVITY

Orientation to avoid Mixing and Double Panel For CBMP Carton Boxes

Attendees						
	FIRST NAME	LAST NAME	DIV. / DEPT. SIGNATURE			
1.	JEFFREY	EDADES	PROD/GLUING			
2.	AMEL LLOYD	GCLTIX	Phen / GWING JEGHT			
3.	MARK RYAW	DULAN	Prod/Gumb Produce			
4.	Jayson	Bual	Prod Gluing found			
5.	Upstoll	NEMEN20	PROD CONVEYDER LU			
6.						
7.						
8.						
9.						
10.						
11.						
12.						
13.						
14.						
15.						
16.						
17.						
18.						
19.						
20						

Note: This form is confidential. Do not use as scratch paper.

Page ____1_ of ____