
INVESTIGATION REPORT FOR DETACHED AT 5164438-01 LUCIDA

DIRECT CAUSE METHOD (PROCESS) W1: During process, putting of B-flute on jig for applying glue and placing C-flute at B-flute after gluing. It is posible to have a weak glue by applying glue without curing time.

METHOD (PROCESS) W2: Placing the pad blocks on PAD BASE after aplying glue, it is posible to detached the pad blocks without putting weights.



PRODUCTION ACTION PLAN

> Trial for curing time c/o production IE





> Orientation for detached pad block to pad block and pad block to pad base.

