
## INVESTIGATION REPORT FOR PAD ASSY INVERTED PAD BLOCK 516444101

DIRECT CAUSE	W1: At Pad assy , operator check the appearance of pad blocks before putting on jig and applying glue. The inverted pad block to pad base occur when the operator skipping or not checking the position of pad block to pad base.
	W2:Theres an scenery that opertor think they attached correct position of pad block to pad base cause of wrong lock of stumb mark at pad block.



JO #: 019121 Input Qty.: 496 Reject Qty.: 2 pcs. Rejection Rate: 0.40%

## **PRODUCTION ACTION PLAN**


- > Re-orientation regarding inverted pad block attached to pad base
- > Placing Golden sample for each table for reference
- >Packing operator will conduct double checking of the side of FG before transfering to QA area for checking.











Back View

