No. 5 R Telepho	NEPACKAG ing Road LISP II, Brgy. La one No. (049) 545-7166 to (049) 545-6302	INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: IRF-08-0002 Date Issued: 11-Aug-22						
Customer	EPPI		Attenti	on To	NOEMI CEPEDA			
Item Code	516513000		Department		KPLIMA-PRODUCTION			
Item Description LIGHT 2 MB A		MERICA	Date of Detection		10-Aug-22			
Job Order Number	19790	19790		n Detected	INLINE QA			
	ILLUSTRATION OF	THE PROBLEM		Major	Minor			
NO. OF OCCURRENCE No.:			Lot Quantity (pcs.) Reject Quantity (pcs.) Reject Percentage 15.43% Nature of Defect: DELAMINATION Requirement: ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF DELAMINATION Actual: DELAMINATION OCCURRED ON THE UPPER FLAP ANG ON THE GLUE TAB PORTION AREA OF OCCURRENCE / ORIGIN AREA OF OCCURRENCE / ORIGIN Slotter Gluing Material EQOS Vertical Dimension Diecut Others: Appearance Process / Method					
Issued by C. Arevalo QA-IE Staff		Checked by Checked by Chylagsino CA Supervisor	Approved b			ے ا	Received by (Receiving Section) N. Cepeda Head/ Supervisor	
		I. INVESTIGA	TION / A	NALYSIS				
Why 1: Why 2: Why 3: Why 4: Why 5:	SE: (Analyze the reaso	on of occurrence, why it happened?)	Why 1: Why 2: Why 3: Why 4: Why 5: Why 1:		SE: (Analyze the re	ason of occur	rence, why it leaked?)	
Why 2: Why 3: Why 4: Why 5:			Why 2: Why 3: Why 4: Why 5:					
Why 1: Why 2: Why 3: Why 4: Why 5:			Why 1 Why 2 Why 3 Why 4	: :	-			

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

			FINAL CON	DEUSION				
00		OUTFLOW ROOTCAUSE						
IMMEDIATE ACTION: (AC	oblem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)						
Sorting Result				Action	ns to be do	ne to eliminate recurrence	Who / Whe	
Loca	tion Total Stock	NG	Total Good					
М				System				
VIP				Oyston				
G							ii ii	
Orientation								
ate Time				Design / Tools				
itle								
Attendees								
. Reworking								
Rework Quantity				Process			5	
otal Good				110000				
Rework Percentage (Good)								
II. QA ROOTCAUSE V	ERIFICATION (To be fille	d out by QA In	n-charge)	Date Conducted:		PIC:		
	Identified Rootcause			Recommendation				
	III. COR	RECTIVE ACT	ION VERIFICATI	ON (To be filled ou	it by QA In	-charge)		
	Checked by E			Implemented?		Remarks		
1st Verification of Action			[]Yes	[]No				
2nd Verification of Action		,	[]Yes	[]No				
3rd Verification of Action			[]Yes	[]No				
Effectiveness of Action			[]Yes	[]No				
Note: If no same defects / deliveries or 3rd verificatio	problems occurs for 5 cons n of action still not yet impl	secutive deliver emented, Inves	ries, corrective ac stigation Report si	tion is considered et hall be re-issued to t	fective / clo	osed. If the same problem oc I department to provide new	curs within 5 consecutive improvement action.	
			IV. CL	OSURE				
Status:	Remarks:		Appro	oved by:		Process Owner Acknowled	Igment: (Receiving Section	
Closed								
Still Open		QA	Supervisor	QA Asst. Mar	nager	Line Leader	Department Head	
Re-Issue IRF		Date:		Date:		Date:	Date:	