No. 5 F Teleph Fax No	INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: IRF-08-0009 Date Issued: 25-Aug-22								
Customer	EPPI		Attention To		NOEMI CEPEDA				
Item Code	51651700		Department		KPLIMA-PRODUCTION				
Item Description	Description CARTON BOX		Date of Detection		24-Aug-22				
Job Order Number	20455		Section Detected		SCREENING				
	ILLUSTRATION OF THE PROBLEM		Major			Minor			
	Lot Quantity (pcs.) Reject Quantity (pcs.) Reject Percentage 20.66% Nature of Defect: TEAR OFF								
	Requirement: ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF TEAR OFF Actual: TEAR OFF OCCURRED ON THE LOCK PORTION								
NO. OF OCCURRENCE		DISPOSITION	AREA OF OCC		CURRENCE / ORIGIN		CONTENT		
First		Hold	Slotter		Gluing	g	Material		
Recurrence		Special Acceptance	EQOS Ve			al	Dimension		
No.:	No.: For Rework		Diecut Others:				Appearance		
Date:		Reject / Disposal	Detaching				Process / Method		
Issued by		Checked by		Approved			Received by (Receiving Section)		
C. Arevalo QA-IE Staff		Magsino QA Supervisor		QA Asst. M	lanager	7/6	N. Cepeda Head/ Supervisor		
		50%的传说,这种特别的一种,但是是一种的。	ATION / ANALYS						
DIRECT CA	USE: (Analyze the reas	on of occurrence, why it happened?)	INDI	RECT CAL	JSE: (Analyze the re	eason of occu	ırrence, why it leaked?)		
Why 1: Why 2: Why 3: Why 4: Why 5:			Why 1: Why 2: Why 3: Why 4: Why 5:						
Why 1:	Why 1:								
Sbuilood Why 2: Why 3: Why 4:		Why 2:							
Why 3:			Why 3:						
Why 4:		Why 4:							
□ Why 5:			Why 5:						
Why 1:			Why 1:						
My 3: Why 4:		Why 2:							
Why 3:	Why 3:			Why 3:					
Why 4:	Why 4:			Why 4:					
© Why 5:	Why 5:								

R

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

			FINAL CONC	CLUSION					
00	CCURRENCE ROOTCAUSE			OUTFLOW ROOTCAUSE					
IMMEDIATE ACTION: (A	ction to be done to contain/ temporar	ry correct the pro	blem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
Sorting Result				Actions to be done to eliminate recurrence Who / Who					
Loca	ition Total Stock	NG	Total Good						
RM									
WIP				System					
G									
Orientation									
Pate		Design /							
Title	Time			Tools					
Attendees									
Reworking									
Rework Quantity									
otal Good				Process					
Rework Percentage (Good)									
THE RESERVE OF THE PARTY OF THE	ERIFICATION (To be filled o	out by QA In-	-charge)	I Date Conducted:_		PIC:			
	Identified Rootcause			Recommendation					
	STEEL STEEL STEEL STEEL STEEL STEELS		CHANGE SHAPE SHAPE	ON (To be filled o	out by QA Ir	BARROLD FOR STATE OF SAME PROBLEM			
Checked by		Date	Implem	ented?		Remarks			
1st Verification of Action		[] Yes [[] No					
2nd Verification of Action		[]Yes		[] No					
3rd Verification of Action			[]Yes	[] No					
Effectiveness of Action	[]Yes		[]No	r.					
Note: If no same defects / deliveries or 3rd verification	 problems occurs for 5 consec n of action still not yet impleme	utive deliveri ented, Invest	es, corrective act igation Report sh	ion is considered all be re-issued to	effective / cl	osed. If the same problem oc d department to provide new i	curs within 5 consecutive improvement action.		
			IV. CLC	SURE					
Status: Remarks:			Approved by			Process Owner Acknowledgment: (Receiving S			
Closed									
Still Open		QA S	Supervisor	QA Asst. Ma	anager	Line Leader	Department Head		
Re-Issue IRF		Date:		Date:		Date:	Date:		