No. 5 I Teleph		E PHILIPPINE INC. a Mesa, Calamba City, Laguna o 69	INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: IRF-09-0001 Date Issued: 07-Sep-22					
Customer	EPPI		Attention To	NOEMI CEPEDA				
Item Code	516387900		Department	KPLIMA-PRODUCTION	KPLIMA-PRODUCTION			
Item Description	LOUVRE 2 M	JX BROWN	Date of Detection	24-Aug-22				
Job Order Number	20268		Section Detected	SCREENING	Processing Street Control of Street			
	ILLUSTRATION OF THE PROBLEM			Major Minor				
EPSON Addition to the state of			Lot Quantity (pcs.) Reject Quantity (pcs.) Reject Percentage 1,000 1 0.10% Nature of Defect: INVERTED AND SAME PANEL A Requirement: ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF INVERTED AND SAME PANEL A Actual:					
			INVERTED AND SAME PANEL A OCCURRED ON THE ITEM					
First Recurrence No.: Date:	ed by	DISPOSITION Hold Special Acceptance For Rework Reject / Disposal Checked by	AREA OF CO Slotter EQOS Diecut Detaching Approx	CCCURRENCE / ORIGIN Gluing Vertical Others:	CONTENT Material Dimension Appearance Process / Method Received by (Receiving Section)			
	C. Alevalo QA-IE Staff QA Supervisor		QA Asst.	N. Cepedia Head/ Supervisor				
			TION / ANALYSIS		and the state of t			
DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?) Why 1: Why 2: Why 3: Why 4: Why 5: Why 5: Why 2:			Why 1: Why 2: Why 3: Why 4: Why 5: Why 1: Why 2:	AUSE: (Analyze the reason of occ	amono, wily il leakeur)			
Why 2: Why 3: Why 4: Why 5: Why 1: Why 2: Why 4: Why 4: Why 4:			Why 3: Why 4: Why 5: Why 1: Why 2: Why 3: Why 4:					

R

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Fax No. (049)				FINAL CON	LUSION			
	ROOTCAUSE			OUTFLOW ROOTCAUSE				
		e						
IMMEDIATE ACTION:	to contain/ temporary	correct the pro	blem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)				
Sorting Result						Actions to be d	one to eliminate recurrence	Who / When
Lo	cation	Total Stock	NG	Total Good	System			
RM								
VIP								
G						36		
Orientation								
Date					Design /			
itle		<u>'</u>			Tools			
Attendees	,							
. Reworking								
Rework Quantity					Process			
otal Good					1 100033			
Rework Percentage (Good)							
II. QA ROOTCAUSE	VERIFICATIO	N (To be filled o	ut by QA In	-charge)	Date Conduc	ted:	PIC:	
	Identified	Rootcause					Recommendation	
		III. CORRE	CTIVE ACTI	ON VERIFICATI	ON (To be fil	led out by QA l	n-charge)	
Checked by		cked by	Date	Implem	Implemented?		Remarks	
1st Verification of Action	erification of Action			[]Yes				
2nd Verification of Action			[]Yes []No					
3rd Verification of Action				[]Yes	[]No			
Effectiveness of Action				[] Yes	[]No			
Note: If no same defect deliveries or 3rd verifica	s / problems occ tion of action sti	curs for 5 consect Ill not yet impleme	utive deliven ented, Inves	ies, corrective ac tigation Report sl	tion is conside hall be re-issu	ered effective / c ed to the affecte	closed. If the same problem of ed department to provide new	ccurs within 5 consecutive improvement action.
		rich de la companya d		IV. CL	OSURE			
Status:	Remarks:			Appro	oved by:		Process Owner Acknowled	dgment: (Receiving Section
Closed								
Still Open			QA	Supervisor	QA As	st. Manager	Line Leader	Department Head
Re-Issue IRF			Date:		Date:		Date:	Date: