


# INVESTIGATION REPORT FOR MISALIGNED CUT OF 516387900 LOUVRE 2 MDX

## DIRECT CAUSE METHOD (MACHINE)

W1: Misaligned cut occurred in the handhole portion with cut on the Japanese character on diecut 1.

W2: There were an issue in the machine when running printed items.

W3: The three gripper were to be replaced and the bearing due to worn out.



## PRODUCTION ACTION PLAN

- > Checking of schedule to engineering for checking the gripper to Sir Peter.
- > Waiting for spare parts.

Prepared by:

PRODUCTION IE

Reviewed by:

Noemi Cepeda  
PRODUCTION SUPERVISOR