KANEPACKAGE PHILIPPINE INC.					INVESTIGATION REPORT FORM (IRF)					
M	Telephone No. (0	49) 545-7166 to	Mesa, Calamba City, Laguna 69	Inhouse Detection			Customer Claim			
Fax No. (049) 545-6302				Contr	ol No.: IRF-10-0016	Date Issued: 25-Oct-22				
Customer EPPI			Attent	ion To	NOEMI CEPEDA					
Item Code -			Depa	rtment	KPLIMA-PRODUCTION					
Item Description PAD BLOCKS			Date	of Detection	22-Oct-22	22-Oct-22				
Job Order Number -			Section	on Detected	LUCIDA QA					
	ILLUS	TRATION OF	F THE PROBLEM		Major		Minor			
					Lot Quantity (pcs.)	Reject Qua		Reject Percentage 60.00%		
GOOD					Nature of Defect: WRONG FLUTE COMBINATION					
F	REJECT			ITEN	ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF WRONG FLUTE COMBINATION					
					Actual:					
1	o- 4 CF stom- 4 BF	Wrong Flute	Top- 3 CF Bottom- 4 BF and 1 CF		WRONG FLUTE COMBINATION OCCURRED ON PAD BLOCKS WITH COMBINATION OF: TOP-4CF; BOTTOM-4BF AND TOP-3CF AND BOTTOM-4BF+1CF					
	NO. OF OCCURREN	CE	DISPOSITION	AREA OF OCCURREN		URRENCE / ORI	GIN	CONTENT		
	First		Hold		Slotter	Gluin	g	Material		
	Recurrence	4-1	Special Acceptance		EQOS	Vertic	al	Dimension		
	No.:		For Rework		Diecut	Other	s:	Appearance		
	Date:		Reject / Disposal		Detaching			Process / Method		
	Issued by		Checked by		Approved I	y		Received by (Receiving Section)		
C. Arevalo G. Magsino QA-IE Staff QA Supervisor				N. Cepeda						
			I. INVESTIGAT	ION / A	NALYSIS	1.154				
	DIRECT CAUSE: (Anal	lyze the reaso	n of occurrence, why it happened?)		INDIRECT CAUS	E: (Analyze the re	ason of occurr	ence, why it leaked?)		
System / Training	Why 1: Why 2: Why 3: Why 4: Why 5:			Why 1 Why 2 Why 3 Why 4 Why 5						
10	Why 1:			Why 1						
Design / Toolings	Why 2:				Why 2:					
7 / 70	Why 3:				Why 3:					
esigr	Why 4:			Why 4	Why 4:					
	Why 5:			Why 5	Why 5:					
	Why 1:		7	Why 1	Why 1:					
Process / Material	Why 2:			Why 2	Why 2:					
, Ma	Why 3:			Why 3	Why 3:					
cess	Why 4:				Why 4:					
A	Why 5:				Why 5:					

R

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69

INVESTIGATION REPORT FORM (IRF)

Fax	No. (049) 545-6302										
		1811		FINAL CON	ICLUSION						
	OCCURREN	ICE ROOTCAUSE				OUTFLOW ROOTCAUSE					
		173%				,N ₁					
IMMEDIATE A	CTION: (Action to be do	ne to contain/ temporary	correct the or	oblem found)	CORREC	CTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
. Sorting Result						Actions to be done to eliminate recurrence Who / Whe					
	Location	Total Stock	NG	Total Good							
RM					_						
WIP					System						
·G					Sq.						
Orientation											
ate		Time			Design /						
itle					Tools						
Attendees		Ţ.									
Reworking											
Rework Quantity											
Fotal Good											
Rework Percentage	e (Good)										
II. QA ROOT	CAUSE VERIFICATI	ION (To be filled ou	it by QA in	-charge)	Date Conduc	cted: PIC:					
Identified Rootcause						Recommendation					
		W copper	NTIVE ACT	AON VERIEIO E							
		hecked by			nented?	lled out by QA in-charge)					
	U U	necked by	Date	impien	ienieu?	Remarks					
1st Verification of Action				[]Yes	[] No						
2nd Verification of Action				[]Yes	[]No						
3rd Verification of Action				[]Yes	[] No						
Effectiveness of Action				[]Yes	[]No						
Note: If no same deliveries or 3rd	defects / problems of verification of action s	ccurs for 5 consecu still not yet implemer	tive deliveri nted, Invest	es, corrective ac ligation Report st	tion is conside nall be re-issu	ered effective / closed. If the same problem occurs within 5 consecutive led to the affected department to provide new improvement action.					
			11 42 1 15 1 165 1	IV. CL	OSURE						
Status:	Remark	s:		Appro	ved by:	Process Owner Acknowledgment: (Receiving Section					
Closed											
Still Open			QA S	Supervisor	QA As	st. Manager Line Leader Department Head					
Re-Issue IRF		l,	Date:	,	Date:	Date:					