

221213

# **INVESTIGATION REPORT**

Prepared By:	Check By:	Approved By:
MHVITO		
OA-IE/ Prodn IE	OA/ Prodn SV	KPLIMA Operations Gen. Mngr.

51	M REVIEW	DOCUMENT REVIEW					
MAN		Affected Document:	Date Reviewed:	Disposition:		PIC:	Target Date:
MACHINE		Procedure Manual			No Revision	MH.VITO	
MATERIAL		Work Instruction		☐ With Revision	No Revision	MH.VITO	
METHOD	NO VERIFICATION OF ITEM AND PROCESS FLOW	Process Flow			No Revision	MH.VITO	
ENVIRONMENT		Forms	OPL	With Revision	□ No Revision	MH.VITO	221214

### I. PROBLEM DESCRIPTION

DATE:

1.1. ISSUE:	
	MIXING OF ITEM
1.2 ITEM DECCRIPTION.	

PART CODE: 5164444101 PART NAME: 1.3. BACKGROUND: LUCIDA ASSY

#### **PICTURE**





# DETAILS:

- > Mixing of item 5164444101 and 51644441001
- > 20 pcs mixed item
- > 20 pcs good
- > Jo#: **026823**
- > Detected by EPPI

# II. IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge			
Re-orient the operator reagarding to the issue of mixed item/model	221124	IE/SUB-LEADER			

#### III. WHY WHY ANLYSIS DETAILS:

- WHY 1: MIXING OF ITEM OCCURRED AT LUCIDA PAD ASSY PACKING PROCESS
  WHY 2: PACKING OPERATOR DID NOT NOTICE THE MIXED ITEM WHILE GETTING TO THE OA INSPECTION TABLE.
- WHY 3: PACKING OPERATOR DID NOT VERIFY IF THE ITEM ARE THE SAME AS THE ITEM RUN AT THAT TIME AND FOCUS ON COUNTING OF ITEMS.

### **INDIRECT CAUSE:**

WHY 1:

WHY 3:

# IV. ACTION PLAN:

- > ORIENT THE OPERATOR REGARDING TO THE ISSUE OF MIXING OF ITEM/MODEL
- > POSTING OPL FOR EYE MARK OR GUIDE FOR PACKING OPERATION/PROCESS.
  > VERIFY THE ITEM BEFORE PACKING BASED ON THE POSTED ITEM RUN. (INCLUDED TO OPL)







1