

☒ PR
☐ VP

ABNORMAL QUALITY NOTICE

SUPPLIER KANEPACKAGE

ATTN

Cc

DEFECT NOTICE CATEGORY

☐ Initial Notice (Information)
☒ Official Notice


ISSUING SECTION PRPE		CONTROL NO.: PRPE-AQN-22-01-0695	ISSUE DATE (Email /Sending Date) 2/1/2023
PARTS INFORMATION		SOURCE OF ABNORMALITY:	
Date/Shift Occurred: 2/1/2023		☐ INCOMING INSPECTION ☐ Source Inspection ☒ PRODUCTION PROCESS ☒ Production (MA) ☐ Production (SA) ☐ Outgoing Inspection (OQA)	
Part Name: LOUVRE 2 MJX ICB FOR CHINA 2		☐ Incoming Inspection ☐ OTHERS ☐ Customer Complaint ☐ Others	
Part Code: 5159133-00		Note: All notice classification issued under AQN requires SAQAR submission.	
Model: S15 LOUVRE 2 MJX		DISPOSITION ON AFFECTED LOT:	
Lot No.: KAN29855D060001		☐ USE AS IS ☐ SPECIAL ACCEPTANCE ☒ RETURN TO SUPPLIER ☒ Rework / Sorting ☒ Disposal	
Lot Qty: 40		☒ HOLD AT EPPI ☒ Rework / Sorting ☐ Disposal (acknowledged by supplier) ☐ OTHERS (pls specify)	
Serial No. (if applicable) n/a		PROBLEM IMPACT CAUSED BY THESE ABNORMALITIES:	
Mold No.: n/a		☐ NO IMPACT ☐ WITH IMPACT ☐ Line Stop / Downtime ☐ Rework / Sort out by	
Cavity ID: n/a		☒ IMPACT NOT YET DETERMINED AT THE TIME OF ISSUANCE	
Defect Name: Wrong Panel (2 codes)		Note: Problem Impact is included in EPPI Failure Cost Monthly Report	
Nature of Defect: ☒ Appearance ☐ Dimension ☐ Functional			
Defect Rate (Pn/n): 5% 2/40			
No of Occurrence: 1st occurrence			

DEFECT DESCRIPTION/ILLUSTRATION (Pls. include defect illustration, lot label and standard vs actual)


Defect Information: Wrong Panel (2 codes)



Different Printer Illustration Color (Black and White)



Different Barcode Label



Initial Investigation/Analysis Results:

During Assembly of LOUVRE 2 MJX model, Main Assembly packing encountered 2 codes on ICB

Disposition on Affected/Other Lots (Supplier):

☒ Sorting / Rework / Hold
☒ Lot Label Markings ALS/
☐ Special Acceptance
☐ Others (pls specify)

Prepared	Checked	Approved	Acknowledgement by Parts in charge:
A. CATIBOG STAFF	A. SULIT SV	K. MIYAZAWA Dept. Head	Name
Date:	Date:	Date:	Target Closure Date

Note:

- (1) AQN must be approved by superior within 24 hours after the defect encountered.
 (2) Suppliers are required to submit Supplier Abnormal Quality Action Report (SAQAR) as follows:
 a) within five (5) working days or as stated on Target Closure Date [Local Suppliers]
 b) within thirty (30) working days or as stated on Target Closure Date [Imported Suppliers]

CONFIDENTIAL

