


Standard procedure of sampling inspection of 1 pc per 10 pcs to detect weak glue on the glue tab portion.

Note: To be included on the work instruction.



Outside checking of
the glue tab portion



Inside checking of the
glue tab portion