K	No. 5 Ring Road	LISP II, Brgy. La M 149) 545-7166 to 69	PHILIPPINE INC. Jesa, Calamba City, Laguna		INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: IRF-23-05-0033 Date Issued: 03-May-23						
Customer	E	PPI		Attentio	То	NOEMI CEPEDA					
Item Code	Code 516041100			Department		KPLIMA- PRODUCTION					
Item Description LIONEL F ASIA				Date of Detection		02-May-22					
Job Order Number 35282				Section Detected		INLINE QA	INLINE QA				
	ILLUS	STRATION OF T	THE PROBLEM	Major		Minor					
ESS	Misaligned cut		Scratches	Lot Quantity (pcs.) Reject Quantity (pcs.) Reject Percentage 7.05% Nature of Defect: MISALIGNED CUT= 2.16% (19/879) DAMAGED= 2.50% (22/879) SCRATCHES= 2.39% (21/879) ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF MISALIGNED CUT/ DAMAGED/ SCRATCHES Actual:							
Elli Barran	Damaged			N	MISALIGNED CUT/ DAMAGED/ SCRATCHES OCCURRED ON THE IT						
	NO. OF OCCURRENCE DISPOSITION			AREA OF OCCURRENCE / ORIGIN			GIN	CONTENT			
F	First		Hold		Slotter	Gluin	g	Material			
F	Recurrence		Special Acceptance		EQOS	Vertic	al	Dimension			
1	No.:		For Rework		Diecut	Other	Screening	Appearance			
ı	Date: Reject / Disposal Issued by Checked by				Detaching			Process / Method			
					Approved by			Received by (Receiving Section)			
م۸ - C. Arevalo QA-IE Staff			G.Magsino GA.Supervisor	ATION / A	QA Asst. Ma	anager	N. Cepeda Head/ Supervisor				
			I. INVESTIGA	ATION / A	NATURE DESIGNATION OF THE PERSON OF THE PERS	SE: (Analyze the r	eason of occu	rrence, why it leaked?)			
527203340		nalyze the reaso	n of occurrence, why it happened?)	Why 1:		oL. (Analyze the N	223011 01 0000	moneo, miy icreateary			
System / Training	Vhy 1: Vhy 2: Vhy 3: Vhy 4:										
	Why 5: Why 1:				Why 5: Why 1:						
	Why 2:			Why 2:							
.8	Why 3:				Why 3:						
sign /	Why 4:				Why 4:						
	Why 5:				Why 5:						
	Why 1:			_	Why 1:						
	Why 2:			Why :	Why 2:						
/ Mat	Why 3:				Why 3:						
Process / Material	Why 4:				Why 4:						
Pro	Why 4: Why 5:				Why 5:						

R

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Fax No. (049) 545			FINAL CONC	LUSION					
00	CURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE			
IMMEDIATE ACTION: (Ad	tion to be done to contain/ temporar	y correct the prob	lem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
. Sorting Result					Actions to be do	one to eliminate recurrence	Who / When		
Loca	tion Total Stock	NG	Total Good						
RM				System					
WIP				System					
-G									
. Orientation									
Date	Time			Design /					
Title				Tools					
Attendees	Land of the state								
. Reworking									
Rework Quantity				Process					
Total Good				1100033					
Rework Percentage (Good)									
II. QA ROOTCAUSE V	ERIFICATION (To be filled o	out by QA In-	charge)	Date Conduct	ed:	PIC:			
	Identified Rootcause					Recommendation			
	III. CORRE	ECTIVE ACTIO	DN VERIFICATIO	ON (To be fill	ed out by QA Ir	n-charge)			
	Checked by	Date	Implem			Remarks			
1st Verification of Action			[]Yes	[]No					
2nd Verification of Action			[]Yes						
3rd Verification of Action		[]Yes		[]No					
Effectiveness of Action			[]Yes	[] No					
Note: If no same defects / deliveries or 3rd verificatio	problems occurs for 5 consents of action still not yet implem	cutive deliverie nented, Investi	es, corrective act gation Report sh	ion is conside all be re-issue	red effective / cl ed to the affecte	osed. If the same problem oc d department to provide new i	curs within 5 consecutive improvement action.		
			IV. CLC				E DESERVE		
Status:	Remarks:		Appro	ved by:		Process Owner Acknowled	gment: (Receiving Section		
Closed									
Still Open		10001-04	Supervisor		st. Manager	Line Leader	Department Head		
Re-Issue IRF		Date:		Date:		Date:	Date:		