K	No. 5 Ring Roa		E PHILIPPINE INC. 1 Mesa, Calamba City, Laguna 69	INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: IRF-23-05-0038 Date Issued: 09-May-23					
	Fax No. (049) !	545-6302							
Custome	er	EPPI		Attention To	NOEMI CEPE	NOEMI CEPEDA			
Item Code 5159121-00				Department	KPLIMA- PRO	KPLIMA- PRODUCTION			
Item Description LOUVRE 2 MJX ICE			X ICB FOR AMERICA	ERICA Date of Detection		09-May-22			
Job Orde	er Number	35693	,	Section Detected	INLINE QA	INLINE QA			
	ILL	USTRATION OF	THE PROBLEM	Major		Mino	r		
			A	Lot Quantity (pcs.)	Reject Qua	antity (pcs.)	Reject Percentage		
90	0 D - 15	400	-2800 EPSU EXGEED YOUR VIS	598 21 3.51% Nature of Defect:			3.51%		
EPSON EPSON	Entwik ET-2800 EP		sectank sectank	PEEL OFF					
			SCOOL K	ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF PEEL OFF					
1	ekn obsul sad (motice)	trace)		Actual:					
	Ass. As a 11 soft i morrofi	American US AN		PEEL OFF OCCURRED DUE TO ENOUNTERED EXCESS GLUE					
NO. OF OCCURRENCE			DISPOSITION	AREA OF O	CCURRENCE / OR	IGIN	CONTENT		
	First		Hold	Slotter Gluing			Material		
	Recurrence		Special Acceptance	EQOS Vertical			Dimension		
No.: For Rework			For Rework	Diecut Others: Appearance					
Date: Reject / Disposal			Reject / Disposal	Detaching Process / Me					
	Issued by Checked by			Approved by Received by (Receiving Section)					
C. Arevalo			G Mag sino			For N. Cepeda			
QA-IE Staff			A Supervisor	QA Asst. Manager		Head/ Supervisor			
			I. INVESTIGA	TION / ANALYSIS					
	DIRECT CAUSE: (A	nalyze the reason	on of occurrence, why it happened?)	INDIRECT CA	JSE: (Analyze the r	eason of occu	rrence, why it leaked?)		
	Why 1:			Why 1:					
rainir	Why 2:			Why 2: —					
System / Training	Why 3:			Why 3:					
Syste	Why 4:			Why 4:					
	Why 5:			Why 5:					
SE SE	Why 1:			Why 1:					
oolii	Why 2:			Why 2:					
Design / Toolings	Why 3:			Why 3:					
Desi	Why 4:			Why 4:					
	Why 5:			Why 5:					
lai	Why 1:			Why 1:					
Process / Material	Why 2:			Why 2: Why 3:					
ess/	Why 3:								
Proce	Why 4:			Why 4:					
Secretar	Why 5:			Why 5:					

No. 5 Telep

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

	阿拉西斯克里斯		FINAL CON	CLUSION				
	DCCURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE		
IMMEDIATE ACTION: (Action to be done to contain/ tempora	ry correct the prol	blem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)				
. Sorting Result			Actions to be done to eliminate recurrence Who / Whe					
Loc	cation Total Stock	NG	Total Good					
RM				Custom				
WIP				System				
FG								
. Orientation								
Date Time				Design /				
Title	itle			Tools				
Attendees		•						
. Reworking								
Rework Quantity				Process				
Total Good				Flocess				
Rework Percentage (Good)								
II. QA ROOTCAUSE	VERIFICATION (To be filled	out by QA In-	charge)	Date Conducted	l:	PIC:		
	Identified Rootcause			Recommendation				
	III. CORR	ECTIVE ACTION	ON VERIFICATI	ON (To be filled	out by QA I	n-charge)		
	Checked by	Date	Implem	ented?		Remarks		
1st Verification of Action			[]Yes []No					
2nd Verification of Action			[]Yes []No					
3rd Verification of Action			[]Yes	[]No				
Effectiveness of Action			[]Yes	[] No				
	/ problems occurs for 5 conse ion of action still not yet implen							
PROPERTY.	HE STATE WELL		IV. CLC	DSURE				
Status: Remarks:			Approved by:		Process Owner Acknowledgment: (Receiving Section)			
Closed		-						
Still Open		QA S	Supervisor	QA Asst. I	Manager	Line Leader	Department Head	
Re-Issue IRF		Date:		Date:		Date:	Date:	