			E PHILIPPINE INC.	INVESTIGATION REPORT FORM (IRF)						
	Telephone No.	(049) 545-7166 to	Mesa, Calamba City, Laguna 69		Inhouse Detection		Custor	mer Claim		
	Fax No. (049) 5	545-6302		Control No.: IRF-23-05-004		Date Issued: 19-May-23				
Custome	er	EPPI		Attention To NOEMI CEPEDA						
Item Cod	m Code 5162982-00 (PANEL B)				Department KPLIMA- PRODUCTION					
tem Description LOUVRE 2 MCX ICB FOR ASIA; C				Date of Detection 18-May-22						
Job Order Number 36600					Section Detected LAMINATION QA					
	ILLU	USTRATION OF	THE PROBLEM		Major Minor					
200000000000000000000000000000000000000				Lo	t Quantity (pcs.)	Reject Qua	ntity (pcs.)	Reject Percentage		
	42.00	/0×32			700	10	0	14.29%		
	II EPSON CALLINO	The second secon	ECOTANK ESITE	Nature of Defect: PEEL OFF						
		Bottom Est Émin 04%	8 Beach	ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF PEEL OFF						
Į,			61829A2000	Actual:						
ATUPISE NATIVO					PEEL OFF ENCOUNTERED DUE TO GLUE STAIN					
	NO. OF OCCURRENCE DISPOSITION				AREA OF OCCURRENCE / ORIGIN CONTENT					
	First		Hold		Slotter	Gluin	g	Material		
	Recurrence Special Acceptance No.: For Rework			EQOS Vertical Dimension						
					Diecut	Other	LAMINATION	Appearance		
	Date:		Reject / Disposal		Detaching			Process / Method		
	Issued by		Checked by	Approved by		ру		Received by (Receiving Section)		
	∂\.r C. Arevalo QA-IE Staff		Magsind A Sopervisor		QA Asst. Man	ager	#00 / H	N. Cepeda Head/ Supervisor		
	经验的	设制的	I. INVESTIGA	ION / A	A THE PARTY OF	= // - -		same why it belied()		
DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)					INDIRECT CAUS	E: (Analyze the re	eason of occurr	rence, why it leaked?)		
Đ.	Why 1:			Why 1: Why 2:						
Traini	Why 2:									
Design / Toolings System / Training	Why 3:									
	Why 4:									
	Why 5:									
	Why 1:									
	Why 2:				Why 2:					
	Why 3:				Why 3:					
	Why 4:			Why 4:						
	Why 5:			Why 5:						
<u>'a</u>	Why 1:				Why 1:					
Process / Material	Why 2:				Why 2:					
SS / N	Why 3:			Why 3:						
roce	Why 4:			Why 4:						
α.	Why 5:			Why 5:						

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

	Vicine Sta	计算数字数	FINAL CONC	CLUSION	TRANSPORT TO SE			
	OCCURRENCE ROOT	CAUSE			OUTFLOW ROOTCAUSE			
IMMEDIATE ACTION:	(Action to be done to contain	n/ temporary correct the	e problem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)				
. Sorting Result				Action	s to be done to eliminate recurrence	Who / When		
Lo	cation Total	Stock NG	Total Good					
RM				System				
WIP								
FG								
. Orientation								
Date	Date Time			Design /				
Title				Tools				
Attendees								
C. Reworking								
Rework Quantity				Process				
Total Good			11000					
Rework Percentage (Good	1)							
II. QA ROOTCAUSI	VERIFICATION (To b	e filled out by QA	A In-charge)	Date Conducted:	PIC:			
	Identified Rootca	use		Recommendation				
		. CORRECTIVE A	CTION VERIFICATI	ON (To be filled out	by QA In-charge)			
	Checked by	Date	e Implem	nented?	Remarks			
1st Verification of Action			[]Yes []No					
2nd Verification of Action			[]Yes []No					
3rd Verification of Action			[]Yes []No					
Effectiveness of Action			[]Yes	[]No				
Note: If no same defect deliveries or 3rd verifica	s / problems occurs for tion of action still not ye	5 consecutive deli et implemented, In	iveries, corrective ac vestigation Report sl	tion is considered effe nall be re-issued to th	ective / closed. If the same problem occ e affected department to provide new in	urs within 5 consecutive nprovement action.		
			IV. CLC	DSURE	建设建设等。1018 里			
Status:	Remarks:		Appro	ved by:	Process Owner Acknowledg	ment: (Receiving Section		
Closed								
Still Open			QA Supervisor	QA Asst. Mana	ger Line Leader	Department Head		
Re-Issue IRF		Date:		Date:		Date:		