KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy, La Mesa, Calamba City, Laguna Telepipone No. (049) 545-7165 in 69		INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: IRF-23-06-0048 Date Issued: 10-Jun-23							
Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302									
Customer	EPPI		Attention To	NOEMI CEPE)A				
llem Code 516181800			Department KPLIMA- PRODUCTION						
Item Description Linus FAL America			Date of Detection 06-Jun-22						
Job Order Number	37614		Section Detected INLINE QA						
	USTRATION OF THE	PROBLEM	Major		Minor				
7 T 9 0	# G+ 35		Lot Quantity (pcs.) 498	Reject Qua		Reject Percentage 12,85%			
EPSON (FEED) EPSON	# 0	Nature of Defect:							
			ITEM SHOULD BE IN G	ood conditic	N; NO OCCU	RRENCE OF CRACKING			
	Actual: SCRATCHES ENCOUNTERED ON THE FOLDING SIDE (PLEASE SEE ATTACHED PICTURE)								
NO. OF OCCURRE	ENCE	DISPOSITION	AREA OF OCCU	IRRENCE / ORI	GIN	CONTENT			
First		Hold	Slotter	Gluin		Material			
Recurrence		Special Acceptance	EQOS	Vertic	al	Dimension			
No.:		For Rework	Diecut	Other	s :	Appearance			
Date:		Reject / Disposal	Detaching			Process / Method			
Issued by	Nederland Ad	Checked by	Approved b	y		Received by (Receiving Section)			
C. Ayfoolo QA-lif Staff		C Magsino DA Supervisor	QA Asst. Mana	ager	A. Capeda Head/ Supervisor				
		I. INVESTIGA	TION / ANALYSIS						
1.5 (4-00 5 - 100 00) (4-14-00) (4-14-00)	nalyze the reason of o	occurrence, why it happened?)	***************************************	: (Analyze the re	eson of occur	rence, why it leaked?)			
Why 1: Why 2: Why 3: Why 4:			Why 2: Why 3:						
₩hy 4: Why 5:			VVhy 4: VVhy 5;						
Why 1: 00 Why 2:			Why 1: Why 2:						
Sb Lilpoot / Uby 3: Why 3: Why 4: Why 5:			Why 3: Why 4: Why 5:						
Why 1:			Why 1: Why 2:			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Why 2: Why 3: Why 4:			Why 3: Why 4:						
Why 5:			Why 5:						

KANEPACKAGE PHILIPPINE INC.
No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69

INVESTIGATION REPORT FORM (IRF)

	x No. (049) 545	-6302								
description			200000	FINAL CONC	LUSION					
	OC	CURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE			
			•							

IMMEDIATE		tion to be done to contain/ temporary	correct the pro	blem found)			ctions to be done to ensure that the pr		*****	
. Sorting Result	<u> Albertan</u>		Harib Carri			Actions to be do	one to eliminate recurrence	- 8 18 18 18 18 18 18 18 18 18 18 18 18 1	Who / Whe	
	Locat	ion Total Stock	NG	Total Good						
RM					System					
WIP										
FG									:	
3. Orientation	igns is grande		VEDV DEN 1993 N							
Date Title		Time			Design / Tools					
Attendees										
C. Reworking			a da se se se							
Rework Quantity	,		- 5 1. 3 1. 3							
Total Good	<u></u>				Process					
Rework Percent	age (Good)									
Augustani Walanda da Jaro Maria Angara Angara	SS-SECTION AND AND AND AND AND AND AND AND AND AN	ERIFICATION (To be filled o	ut by QA In	-charge)	Date Conduct	 ∋d;	PIC:		<u></u>	
	9/22/2010	Identified Rootcause			Recommendation					
		•								
		III. CORRE	CTIVE ACTI	ON VERIFICATION	ON (To be fill	ed out by QA In	ı-charge)			
		Checked by	Date	lmplem	ented?		Remarks			
1st Verification	n of Action			[]Yes	[] No					
2nd Verificatio	n of Action			[]Yes	[] No					
3rd Verificatio	3rd Verification of Action [] Yes			[]Yes	[] No					
Effectiveness	s of Action			[]Yes	[] No	ļ				
Note: If no sa	me defects / j	problems occurs for 5 consect	utive deliveri	ies, corrective act	ion is conside	red effective / cl	osed. If the same problem occ d department to provide new ir	urs within 5 o	consecutive action	
uenvenes or .	ora vormeallor	, or action and not yet impleme	zinou, mycal		\$45500 AND BENEFIT (AND BENEFIT	_ to the another				
	Status: Remarks:				OSURE oved by:		Process Owner Acknowledgment: (Receiving Section			
Status:	CERTIFICATION IN	кепака;	MICHAEL STATES	Appro	vea by.		Lineara Catter Vertionied	lineiir (Lece	uvii iğ Sectio	
Closed Still Open	Initial requirement of EPPI= 168 pcs.		QA Supervisor		QA Asst. Manager		Line Leader	Departe	ment Head	