

NEW blade size: 30mm Replacement size: 21mm Actual size 20mm



	ENGIN	NEERING & MAII	NTENANCE D	)EPAF	RTMENT	
					Control No:	WR-0121
	0	RIGINATOR TO F	ILL-UP SPACE	BELO	ow	
	X General M		Г		hicle Repair	
Unit Name:	Department/Ar	Department/Area:				
VERTICAL MACHINE BL	ADE	KP LIMA PROD	KP LIMA PRODUCTION			N/A
Model:		Location:	Location:			Date Needed:
N/A		KP LIMA	KP LIMA			2023-06-08
REQUEST / COMPLAINT	S (State the problem	/ Failure / Observation	/ Request / Other	rs / Atta	ch drawing if neces	sary)
DAMAGED VERTICAL	MACHINE BLADE (M	ACHINE 3 AND 4)				
Originator:		Approved by:			Receive by(Engineering):	
VITO, MARK HENRY   2023-06-07		CEPEDA, NOEMI V.   2023-06-08		MACATANGAY, EMAR   2023-06-08		
Signature over Printed Name & Date		Signature over Printed Name & Date		ate	Signature over Printed Name & Date	
		ENGINEERING TO	FILL JIP SPACE R	FLOW		
	X In-house	ENGINEERING TO		ice Prov	rider:	
Date Requested: 2023-06-07   Schedule Date: 2023-06-08   Work Decription (Action to be taken)		Date Started: Date Completed:		2023-06-08 2023-06-08 11:17:19		
Replacement of worn	out blade					
		Material	/ Parts Usage			
Descr		Qty		Unit	Total Cost	
Desci	ipuona / opacincauoi		ay	_	Oille	TOTAL COST
		Service Prov	vider / Other Cost			
Description	ons / Specifications	P.0	D. No	Qty	Unit	Total Cost
Ongoi	ng	Status of Hold	Work Request	X ot	her: Work Done	
Remarks:						
Assigned To / Done By:		Checked by:			Accepted by (Originator):	
MACATANGAY, JETHRO		MACATANGAY, EMAR   2023-06-08			VITO, MARK HENRY   2023-06-09	
Signature over Printed Name & Date		Signature over Printed Name & Date			Signature over Printed Name & Date	