

DATE:

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT

lo. (049) 545-7166 to 69	Prepared By:	Check By:	Approved By:	
9) 545-6302				
JUNE 23, 2023	K.DIAZ	N. CEPEDA	R. MIRANDA	
<u>JONE 23; 2023</u>	QA-IE/ Prodn IE	QA/ Prodn SV	KPLIMA Operations Gen. Mngr.	

DOCUMENT REVIEW

_						
MAN	No Changes	Affected Document:	Date Reviewed:	Disposition:	PIC:	Target Date:
MACHINE	No Changes	Procedure Manual		With Revision V No Revision	K. DIAZ	N/A
MATERIAL	WORN OUT PATTERN SHEET	Work Instruction	230616	With Revision V No Revision	K. DIAZ	N/A
METHOD	No Changes	Process Flow	230010	With Revision V No Revision	K. DIAZ	N/A
ENVIRONMENT	No Changes	Forms		With Revision V No Revision	K. DIAZ	N/A

I. PROBLEM DESCRIPTION

5M REVIEW

1.1. ISSUE:				
	PEEL OFF			
1.2. ITEM DESCRIPTION	l:			
PART CODE:	PART CODE: 516513000			
PART NAME:	LIGHT 2 MB AMERICA			
1.3. BACKGROUND:				
PICTURE	<pre>>Inhouse Detection : PEEL OFF >Lot size: 1069pcs > Reject Qty: 45pcs > Rejection Rate: 4.21%</pre>			

IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge
PUT BACKING TAPE ON THE UNCUT PORTION OF TH ITEM.	JUNE 14, 2023	PIC: OPERATOR AND SUBLEADER

III. CAUSE ANALYSIS:

WHY 1:	PEEL OFF DUE TO THE ITEM BECOMING UNCUT WHILE THE MACHINE WAS IN OPERATION.	
	WHEN WE CHECKED THE BLADE, THE BLADE WAS STILL OK, BUT THE PATTERN SHEET (PATCHING AND BACKING TAPE) WAS WORN OUT DUE TO EXCESSIVE USE.	
WHY 3:	THE OPERATOR CONTINUED TO USE THE PATTERN SHEET BECAUSE THEY BELIEVED WHAT THEY WERE PERFORMING WAS OK.	

IV. ACTION PLAN:

V. EVIDENCES:

1	RE-EDUCATE THE OPERATOR ON THE CORRECT APPLICATION OF THE MATERIALS OR TOOLS THEY USE.
2	SUBLEADER WILL BE CONCERNED TO REQUEST TOOLING CUSTODIAN FOR REPLACEMENT TOOLS OR EQUIPMENTS
3	POST OPL ABOUT USING PATTERN SHEET AND BACKING TAPE (APPERANCE)