



Repairing of bearing

Minutes of Meeting

K KANEPACKAGE PHILIPPINE INC.			
MINUTES OF THE MEETING			
Date	Time	Time	Venue
2014.11	Start	Finished	0001 Audit Meeting
ATTENDEES:			
Name	Dept.	Sign	Name
Beland Nonda	Prod	[Signature]	
Alfred C. Aranda	Prod	[Signature]	
Alfred D. Aranda	Prod	[Signature]	
Edison B. Aranda	Prod	[Signature]	
Francis C. Aranda	Prod	[Signature]	
Francis C. Aranda	Prod	[Signature]	
AGENDA:			
TO DISCUSS: GLUE (MAIN ITI GLUE) IN ITEM CODE 91042800 (LIGHT TA EUROPE R.2)			
MINUTES:			
WHY 1: because glue encountered in item code 91042800 (LIGHT TA EUROPE R.2) during mass production in semi auto gluing.			
WHY 2: because glue happen due to worn out bearing of 1st gluing.			
WHY 3: because the bearing of 1st gluing is already wiggled during application of glue.			
FOLLOW UP MEETING:			
(Date & time)			
For KPMI fill up only			
Prepared by:	Reviewed by:	Noted by:	