

**KANEPACKAGE PHILIPPINE INC.**


No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)☒ Inhouse Detection☐ Customer Claim

Control No.: IRF-23-06-0057

Date issued: 29-Jun-23

Customer	EPPI	Attention To	NOEMI CEPEDA
Item Code	516512900	Department	KPLIMA- PRODUCTION
Item Description	LIGHT 2 MB AMERICA	Date of Detection	26-Jun-22
Job Order Number	38949	Section Detected	INLINE QA

ILLUSTRATION OF THE PROBLEM☐ Major☒ Minor

Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage
1,168	148	12.67%

Nature of Defect:

PEEL OFF

ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF PEEL OFF

Actual:

PEEL OFF ENCOUNTERED ON THE UPPER FLAP CLASS B
(PLEASE SEE ATTACHED PICTURE)

NO. OF OCCURRENCE	DISPOSITION	AREA OF OCCURRENCE / ORIGIN	CONTENT
<input checked="" type="checkbox"/> First	<input type="checkbox"/> Hold	<input type="checkbox"/> Slotter	<input type="checkbox"/> Material
<input type="checkbox"/> Recurrence	<input type="checkbox"/> Special Acceptance	<input type="checkbox"/> EQOS	<input type="checkbox"/> Dimension
No.:	<input type="checkbox"/> For Rework	<input type="checkbox"/> Diecut	<input type="checkbox"/> Appearance
Date:	<input checked="" type="checkbox"/> Reject / Disposal	<input type="checkbox"/> Detaching	<input checked="" type="checkbox"/> Process / Method
Issued by	Checked by	Approved by	Received by (Receiving Section)
 C. Arevalo QA-IE Staff	 G. Maglino QA-Supervisor	 QA Asst. Manager	 N. Cepeda Head/ Supervisor

I. INVESTIGATION / ANALYSIS

DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)		INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)	
System / Training	Why 1:		Why 1:
	Why 2:		Why 2:
	Why 3:		Why 3:
	Why 4:		Why 4:
	Why 5:		Why 5:
Design / Toolings	Why 1:		Why 1:
	Why 2:		Why 2:
	Why 3:		Why 3:
	Why 4:		Why 4:
	Why 5:		Why 5:
Process / Material	Why 1:		Why 1:
	Why 2:		Why 2:
	Why 3:		Why 3:
	Why 4:		Why 4:
	Why 5:		Why 5:

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**FINAL CONCLUSION**

OCCURRENCE ROOTCAUSE	OUTFLOW ROOTCAUSE

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)**CORRECTIVE ACTION:** (Actions to be done to ensure that the problem will not happen again)

A. Sorting Result					Actions to be done to eliminate recurrence		Who / When
	Location	Total Stock	NG	Total Good	System		
RM							
WIP							
FG							
B. Orientation					Design / Tools		
Date		Time					
Title							
Attendees							
C. Reworking					Process		
Rework Quantity							
Total Good							
Rework Percentage (Good)							

II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)

Date Conducted: _____ PIC: _____

Identified Rootcause	Recommendation

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked by	Date	Implemented?	Remarks
1st Verification of Action			[] Yes [] No	
2nd Verification of Action			[] Yes [] No	
3rd Verification of Action			[] Yes [] No	
Effectiveness of Action			[] Yes [] No	

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE

Status:	Remarks:	Approved by:		Process Owner Acknowledgment: (Receiving Section)	
<input type="checkbox"/> Closed	Initial requirement of EPPI= 168 pcs. No available RM Stocks of SF Next Plan: Possible December 2023				
<input type="checkbox"/> Still Open		QA Supervisor	QA Asst. Manager	Line Leader	Department Head
<input type="checkbox"/> Re-Issue IRF		Date:	Date:	Date:	Date: