


WRITTEN EXPLANATION ABOUT WHAT HAPPENED IN GLUE STAIN IN ITEM CODE 516512800 (LIGHT FB AMERICA)



POSSIBLE PLACEMENT OF RUBBER ROLLER IN MACHINE GLUING 3 TO FLATTEN THE WARP ITEM