

**KANEPACKAGE PHILIPPINE INC.**


No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna  
Telephone No. (049) 545-7166 to 69  
Fax No. (049) 545-6302

**INVESTIGATION REPORT FORM (IRF)**☒ Inhouse Detection☐ Customer Claim

Control No.: IRF-23-08-0073

Date Issued: 26-Aug-23

Customer	EPPI	Attention To	NOEMI CEPEDA
Item Code	5150488-00	Department	KPLIMA- PRODUCTION
Item Description	Carton Box PL1795F	Date of Detection	230825 DS
Job Order Number	JO-043169	Section Detected	DIECUT QA IN-PROCESS

**ILLUSTRATION OF THE PROBLEM**

<input type="checkbox"/> Major	<input checked="" type="checkbox"/> Minor	
Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage
196	114	58.16%

Nature of Defect:

WRONG BLADE USE

ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF WRONG BLADE USE

Actual:

WRONG BLADE USE WAS ENCOUNTERED ON THE ITEM  
(PLEASE SEE ATTACHED PICTURE)

NO. OF OCCURRENCE	DISPOSITION	AREA OF OCCURRENCE / ORIGIN	CONTENT
<input checked="" type="checkbox"/> First	<input type="checkbox"/> Hold	<input type="checkbox"/> Slotter	<input type="checkbox"/> Material
<input type="checkbox"/> Recurrence	<input type="checkbox"/> Special Acceptance	<input type="checkbox"/> EQOS	<input type="checkbox"/> Dimension
No.:	<input type="checkbox"/> For Rework	<input checked="" type="checkbox"/> Diecut	<input type="checkbox"/> Appearance
Date:	<input checked="" type="checkbox"/> Reject / Disposal	<input type="checkbox"/> Detaching	<input checked="" type="checkbox"/> Process / Method
Issued by	Checked by	Approved by	Received by (Receiving Section)
C. Arevalo QA-IE Staff	G. Magsino QA Supervisor	QA Asst. Manager	No Cepeda Head/ Supervisor

**I. INVESTIGATION / ANALYSIS**

DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)		INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)	
System / Training	Why 1:	Why 1:	
	Why 2:	Why 2:	
	Why 3:	Why 3:	
	Why 4:	Why 4:	
	Why 5:	Why 5:	
Design / Toolings	Why 1:	Why 1:	
	Why 2:	Why 2:	
	Why 3:	Why 3:	
	Why 4:	Why 4:	
	Why 5:	Why 5:	
Process / Material	Why 1:	Why 1:	
	Why 2:	Why 2:	
	Why 3:	Why 3:	
	Why 4:	Why 4:	
	Why 5:	Why 5:	

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna  
Telephone No. (049) 545-7166 to 69  
Fax No. (049) 545-6302

**INVESTIGATION REPORT FORM (IRF)****FINAL CONCLUSION****OCCURRENCE ROOTCAUSE****OUTFLOW ROOTCAUSE****IMMEDIATE ACTION:** (Action to be done to contain/ temporary correct the problem found)**CORRECTIVE ACTION:** (Actions to be done to ensure that the problem will not happen again)**A. Sorting Result**

	Location	Total Stock	NG	Total Good
RM				
WIP				
FG				

Actions to be done to eliminate recurrence

Who / When

System

Design /  
Tools

Process

**B. Orientation**

Date		Time	
Title			
Attendees			

**C. Reworking**

Rework Quantity	
Total Good	
Rework Percentage (Good)	

**II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)**

Date Conducted: \_\_\_\_\_ PIC: \_\_\_\_\_

Identified Rootcause

Recommendation

**III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)**

	Checked by	Date	Implemented?	Remarks
1st Verification of Action			[ ] Yes [ ] No	
2nd Verification of Action			[ ] Yes [ ] No	
3rd Verification of Action			[ ] Yes [ ] No	
Effectiveness of Action			[ ] Yes [ ] No	

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

**IV. CLOSURE**

Status:	Remarks:	Approved by:		Process Owner Acknowledgment: (Receiving Section)	
<input type="checkbox"/> Closed	Initial requirement of EPP= 168 pcs. No available RM Stocks of SF Next Plan: Possible December 2023	QA Supervisor	QA Asst. Manager	Line Leader	Department Head
<input type="checkbox"/> Still Open		Date:	Date:	Date:	Date:
<input type="checkbox"/> Re-Issue IRF					