	No. 5 Ring Ro	ad LISP II, Brgy. La . (049) 545-7166 to	E PHILIPPINE INC. Mesa, Calamba City, Laguna 69	INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: IRF-23-00089 Date issued: 18-Oct-23					
Custome		EPPI		Attention To	N. CEPEDA/ R.				
Item Cod	en de la composición	5151436-00		Department KPLIMA- PRODUCTION					
Item Des	<u>ang Palatan pangkan palatan</u> Palatan pangkan	CARTON BOX		Date of Detection 231017 DS					
1,5,15-15	r Number	047151		Section Detected IN-PROCESS DIE CUT					
	es eta tragas establica. Esta a managon establica (1997)		THE PROBLEM	Major					
				Lot Quantity (pcs.) 189 37 19.58% Nature of Defect:					
B-436	EPSON		SOU DESCN BASED	ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF INVERTED DIE CUT Actual: INVERTED DIE CUT WAS ENCOUNTERED ON THE ITEM (PLEASE SEE ATTACHED PICTURE)					
	NO. OF OCCURR First Recurrence No.: Date:	ENCE	DISPOSITION Hold Special Acceptance For Rework Reject / Disposal Checked by	AREA OF OCCU Slotter EQOS Diecut Detaching Approved b	JRRENCE / ORIC Gluing Vertice Others	al s:	CONTENT Material Dimension Appearance Process / Method Received by (Receiving Section)		
J)Tapay QA-IE Staff			QA Supervisor	QA Asst. Man	ager	N. Cepfeda/ R. Almarlo Head/ Supervisor/ Manager			
+11545-1577	DIRECT CAUSE: (A		I. INVESTIGAT on of occurrence, why It happened?)	ION / ANALYSIS			rrence, why it leaked?)		
System / Training	Why 1: Why 2: Why 3: Why 4: Why 5:			Why 1: Why 2: Why 3: Why 4: Why 5:					
Design / Toolings	Why 1: Why 2: Why 3: Why 4:			Why 1: Why 2: Why 3: Why 4: Why 5:					
Process / Material	Why 5: Why 2: Why 3: Why 4: Why 5:			Why 1: Why 2: Why 3: Why 4: Why 5:					

KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LTSP II, Brgy, La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

					FINAL CONC	CLUSION				
	00	COURRENCE ROOT	CAUSE					OUTFLOW ROOTCAUSE		
										!
		· · · · · · · · · · · · · · · · · · ·								
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)						CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)				
A. Sorting Result	suit					Actions to be done to eliminate recurrence Who / When				
	Loca	tion Total	Stock	NG	Total Good					
RM						System				
WIP					-	•				
FG								1 11 11 11 11		
B. Orientation										
Date		Ti	ne			Design /				1
Title		24 Acrit (2014) 1 Acr	·,··,			Tools				
Attendees								, , , , , , , , , , , , , , , , , , ,		
C. Reworking										:
Rework Quantil	ty					Process				
Total Good						1 100000				
Rework Percen	itage (Good)									
II. QA RO	OOTCAUSE V	ERIFICATION (To be	filled c	out by QA In-c	harge)	Date Conduct	ed:	PIC:		_
		Identified Rootcal	se			Recommendation				
	*									
		V.	0m01/3d23/30m256			III.ONTEPONAL WILLOWALIGUE	2002-2011-2011-2011-2011-2011-2011-2011			
		III.	CORRE	CTIVE ACTIC	N VERIFICATI	ON (To be fill	ed out by QA I	n-charge)		
		Checked by		Date Implen		mented?		Remarks		
1st Verificatio	on of Action	,			[]Yes					
rot vormound	an or Alonon					[] No				
2nd Verification of Action		[]Yes			[] No					
Ziid Voiiiiodiii			[[] fes			4 Jiio				
3rd Verification of Action				[]Yes		[]No				
Effectiveness of Action			[] Yes		[] No					
							1			
								losed. If the same problem oc d department to provide new i		
					IV. GLO	SURE				
Status: Remarks:				Appro	oved by:		Process Owner Acknowled	gment: (Recei	ving Section)	
Closed			nec							
Still Open No ava		nitial requirement of EPPI= 168 pcs. No available RM Stocks of SF			QA Supervisor		t. Manager	Line Leader	Deparlm	ent Head
		: Possible December	Date:				Date:	Date:		