


THE BELT MOVE SIDEWAYS



THE BELT GOES INTO THE CHAIN



KANEPACKAGE PHILIPPINE, INC.

WORK REQUEST
ENGINEERING & MAINTENANCE DEPARTMENT

Control No: WR-0653

Vehicle Repair Vehicle Repair Unit Name: Department/Area: Plate No. / Ref No: SEMI AUTO GLUING MACHINE 2 & 3 KP LIMA PRODUCTION N/A Model: Location: Date Needed:
SEMI AUTO GLUING MACHINE 2 & 3 KP LIMA PRODUCTION N/A
Model: Date Mandad:
moder. Location: Date Needed:
UEDA KP LIMA 2023-10-13
REQUEST / COMPLAINTS (State the problem / Failure / Observation / Request / Others / Attach drawing if necessary)
REQUESTING OF UPPER AND LOWER SANDWICH CONVEYOR BELT
Originator: Approved by: Receive by(Engineering):
ACUIN, KYLAH NICOLE 2023-10-03 CEPEDA, NOEMI V. 2023-10-03 BAGUILAT, JASRAEL L. 2023-10-04
Signature over Printed Name & Date Signature over Printed Name & Date Signature over Printed Name & Date
ENGINEERING TO FILL-UP SPACE BELOW
In-house X Service Provider: Bengar Industrial Corporation
Date Requested: 2023-10-03 Date Started: 0000-00-00
Schedule Date: 2023-11-11 Date Completed: No Specified Date Yet
Work Decription (Action to be taken)
Purchase of two sets of sandwich conveyor.
Material / Parts Usage
Descriptions / Specifications
Service Provider / Other Cost
Descriptions / Specifications P.O. No Qty Unit Total Cost
Status of Work Request Ongoing Hold Other: Remarks:
Assigned To / Done By: Checked by: Accepted by (Originator):
MACATANGAY, EMAR
Signature over Printed Name & Date Signature over Printed Name & Date Signature over Printed Name & Date

