No. 5 Ri	ng Road LISP II, Brgy. L	SE PHILIPPINE INC. a Mesa, Calamba City, Laguna	INVESTIGATION REPORT FORM (IRF)					
	ne No. (049) 545-7166 t (049) 545-6302	o 69	Inhouse Detection Customer Claim Control No.: IRF-23-11-112 Date Issued: 21-Noy-23					
Customer	EPPI		Attention To N. CEPEDA/ R. ALMARIO					
tem Code	5149640-00		Department	KPLIMA- PRODUCTION				
tem Description			Date of Detection 231120 DS					
Job Order Number 049918			Section Detected SCREENING					
	ILLUSTRATION O	F THE PROBLEM	Major Minor					
			Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage			
A A STATE OF			453	141	31.13%			
			Nature of Defect:					
EPSON YED	EPSON YOU			WRONG SLOT				
No the Misses			ITEM SHOULD BE IN (GOOD CONDITION; NO OCCL	JRRENCE OF WRONG SLOT			
Faces			Actual:					
				SLOT WAS ENCOUNTERED PLEASE SEE ATTACHED PIC				
NO. OF OCCURRENCE		DISPOSITION		Slotter	CONTENT			
First		Hold	Slotter Gluing		Material			
Recurrence		Special Acceptance	EQOS Vertical		Dimension			
No.:		For Rework	Diecut Others: Appearance					
Date:		Reject / Disposal	Detaching		Process / Method			
Issued by		Checked by	Approved	by	Received by			
J.Tapay QA-IE Staff		G. Magsing of Supervisor	QA Asst. Mar		. 01/2			
DIRECTICALIS	E: (Analyza the rece	I. INVESTIGE on of occurrence, why it happened?)	ATION / ANALYSIS	CE: (Analyze the reason of age	uurranea why it lagkad?)			
Why 1:	L. (Allalyze tile leas	on of occurrence, why it happened?)	INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?) Why 1:					
Why 2:			Why 2:					
My 3: Why 3: Why 4:			Why 3:					
			Why 4:					
Why 5:			Why 5:					
Why 1:			Why 1:					
. <u>:</u> Why 2:			Why 2:					
Why 2: Why 3: Why 4:			Why 3:					
			Why 4:					
Why 5:			Why 5:					
Why 1:			Why 1:					
My 3: Why 4:			Why 2:	Why 2:				
Why 3:			Why 3:	Why 3:				
Why 4:			Why 4:	Why 4:				
Why 5:			Why 5:	Why 5:				

KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Tax No. (049) 34	atota sila sika di da inda inda	and the same	FINAL CO	ACTURION 1	to be at a transfer of the second section of the		
	CCURRENCE ROOTCAUSE		FINAL CO.	NOTOSION	OUTFLOW ROOTCAUSE		
	SOUTHER TO TO AGGE				CONTENTINECTORICS		
IMMEDIATE ACTION: (A	ction to be done to contain/ temporar	ry correct the pro	oblem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)			
. Sorting Result				Actio	ns to be done to eliminate recurrence	Who / Whe	
Loca	tion Total Stock	NG	Total Good	System			
RM							
VIP				System			
G							
Orientation							
Pate	Time			Design / Tools			
itle							
Attendees							
Reworking							
Rework Quantity				Process			
otal Good				,,,,,,,			
Rework Percentage (Good)							
II. QA ROOTCAUSE V	ERIFICATION (To be filled	out by QA In	-charge)	Date Conducted:	PIC:		
	Identified Rootcause			Recommendation			
				×1.			
	III. CORR	RECTIVE ACT	TION VERIFICAT	TION (To be filled ou	t by QA In-charge)		
	Checked by	Date	Impler	emented? Remarks			
1st Verification of Action	t Verification of Action [] Yes		[]No				
2nd Verification of Action			[]Yes []No				
3rd Verification of Action			[]Yes []No				
Effectiveness of Action			[]Yes	[] No			
Note: If no same defects / deliveries or 3rd verification	problems occurs for 5 consec n of action still not yet implem	cutive deliven nented, Inves	ies, corrective ac tigation Report s	tion is considered effe hall be re-issued to th	ective / closed. If the same problem occurs within e affected department to provide new improveme	5 consecutive ent action.	
A CHARLE			IV. CI	LOSURE		a was kee	
Status:	Remarks:		Appro	oved by:	Process Owner Acknowledgment: (F	Receiving Section	
Closed							
Still Open		QA :	Supervisor	QA Asst. Mana	ger Line Leader D	epartment Head	
Re-Issue IRF		Date:		Date:	Date: Date:		