

KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (043) 545-7166 to 69 Fax No. (043) 545-6302		<h2 style="margin: 0;">INVESTIGATION REPORT</h2>		
DATE: 240111		Prepared By: MHVITO QA-IE/ Prodn IE	Check By: N. CEPEDA Production supervisor	Approved By: RALMARIO Production Manager

5M REVIEW		DOCUMENT REVIEW			
MAN	No Changes	Affected Document:	Date Reviewed:	Disposition:	PIC:
MACHINE	No Changes	Procedure Manual	240111	<input type="checkbox"/> With Revision <input checked="" type="checkbox"/> No Revision	MH VITO
MATERIAL	No Changes	Work Instruction		<input checked="" type="checkbox"/> With Revision <input type="checkbox"/> No Revision	MH VITO
METHOD	CYREL CANAL	Process Flow		<input checked="" type="checkbox"/> With Revision <input checked="" type="checkbox"/> No Revision	MH VITO
ENVIRONMENT	No Changes	Forms		<input type="checkbox"/> With Revision <input checked="" type="checkbox"/> No Revision	MH VITO
					Target Date:
					N/A
					240229
					N/A
					N/A

I. PROBLEM DESCRIPTION

1.1. ISSUE:
 FADED CHARACTER

1.2. DETAIL
PART CODE: 5167137-00
PART NAME: INDIVIDUAL CARTON BOX

1.3. BACKGROUND:

PICTURE 	DETAILS: <ul style="list-style-type: none"> > PLAN QTY: 587 PCS > REJECT QTY: 40 PCS > REJECT PERCENTAGE: 6.81% > JO #: 053454
--------------------	--

II. IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge
ORIENTATION REGARDING INCOMPLETE PRINT ISSUE	240111	PRODUCTION

III. CAUSE ANALYSIS:

WHY'S	DETAIL	IMAGE
WHY 1:	Why Faded character occur at item 5167137-00 Individual Carton Box? The ink that was distributed was not able to penetrate in the cyrel	
WHY 2:	Why the ink cannot penetrate in the cyrel? Some parts of the cyrel particular on the affected image are not touch/ fit on the board	
WHY 3:	Why some parts of the cyrel are not touch/fit on the board? Machine cylinder has canal which is aligned on the cyrel character that cause faded print	
WHY 4:	Why the machine cylinder has canal? Upon installation of the machine, It used to hang small cyrel and it has meter tape canal for measurement to aligned the cyrel on the cylinder.	
WHY 5:		

IV. ACTION PLAN:

V. EVIDENCES:

1	PUTTING OF BACKING TAPE AT METER TAPE CANAL AND CYREL STICK ON PRINTING STRIP CANAL.		240111
2	INCLUSION IN WORK INSTRUCTION ON PUTTING OF BACKING TAPE AT METER TAPE CANAL AND CYREL STICK ON PRINTING STRIP CANAL.		240229