

## Investigation Report for Misalign Print of Sanyo Denki 00972065-01 Top Pad

CONTROL No:	IRF - 0035			REJECT PERCENTAGE:	37.50%
REJECT QTY:	90	LOT QTY:	240		

DIRECT CAUSE	W1	THERE'S A LATERAL PRINTING MOVEMENT DURING EQOS PROCESS
	W2	UNEVEN WIDTH SIZE OF CUTTED BOARDS
	W3	UNEVEN CUTTING DURING SLITTER PROCESS

### PRODUCTION ACTION PLAN

CORRECTIVE ACTION	REPLACEMENT OF OLD SLITTER SMALL	PIC:	Production Leader	TARGET DATE:	250120
CORRECTIVE ACTION	USE OF NEW AUTO SLITTER	PIC:	Production Leader	TARGET DATE:	250120

PREPARED BY:

GERALD DE GUZMAN  
PROD SUPERVISOR

APPROVED BY:

REXEL ALMARIO  
PROD MANAGER