

Investigation Report for Worn Out & Peel off of Denso PH989702-0721 Box

CONTROL No:	IRF - 0056			REJECT PERCENTAGE:	2.86%
REJECT QTY:	20	LOT QTY:	700		

DIRECT CAUSE	W1	The edges of the board hits the feeder gate of Eqos that caused Worn Out & Peel Off.
	W2	The edges of the board are delaminated up to 3-5mm.



PRODUCTION ACTION PLAN

IMMEDIATE ACTION	Eqos feeder conduct pre-folding upon detection. (This action is temporarily since its effect on the productivity)	PIC:	Production	TARGET DATE:	250131
CORRECTIVE ACTION	Coordinate the issue to Supplier, SunPack (C/O QA)	PIC:	QA	TARGET DATE:	

PREPARED BY:

GERALD DE GUZMAN
PROD SUPERVISOR

APPROVED BY:

REXEL ALMARIO
PROD MANAGER