KANEPACKAGE PHILIPPINE INC.			INVESTIGATION REPORT FORM (IRF)						
Telepho	one No. (049) 5457-7	yy. La Mesa, Calamba City, Laguna 166 to 69	Control I	No.:	[Date Issued			
Fax No.	. (049) 545-6302	0014		241010					
Customer	CANON BUSINES	S MACHINE PHILS.	Attention To WEENA APALLA						
Item Code	3CB-0004-000	Department PRODUCTION							
Item Description	PARTITION		Date of Detection 241005						
Job Order Number	JO-F-24-819-2		Section Detected QA SCREENING						
1	LLUSTRATION C	OF THE PROBLEM							
					Qty (pcs)	Reject %			
1777	G		Nature of Defect:						
			SCORING						
			Requirement:						
	\ 1 1		There should be no scoring						
			Actual						
	: Heavy scori EMENT: Ther	ng re should be no scoring	Heavy scoring						
NO. OF OCCURENCE		DISPOSITION	AREA OF OCCURENCE / OF		IGIN	CONTENT			
First		Hold	Slotter Gluin						
Recurrence No.: 1		Special Acceptance For Rework	EQOS Vertica Diecut Others		A				
ı	Date.: _241005_	Reject / Disposal	Detaching	Others		Process / Method			
Issued	Issued by Cl		Approved	l by	Received by (Receiving Section)				
LESTER JOHN DI	OSO 241010	CHARLENE JAN MARIE FLORES 241011	MICHAEL CASILLA	NO 241015	GERALD I	DE GUZMAN 241016			
		I. INVESTIGATION	/ ANALYSIS						
	nalyze the reasor	of occurence, why it happened?)							
System / Training									
Design / Toolings									
Process / Material									



INVESTIGATION REPORT FORM (IRF)

Department Head

INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)											
Syste	m / Trai	ning									
Desig	n / Tool	ings									
Proces	ss / Mat	terial									
CORRI	CTIVE	ACTION: (Action	a ta ba dana			ONCLUSION			WILL / WILLIAM		
CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again) WHO / WHEN											
IMME	DIATE A	CTION: (Action	to be done to	contain/ te	emporary cor	rect the problem	1 foun	nd)			
A. Sort	ing Resu	ult				C. Reworking					
		Location	Total Stock	NG	Total Good	Rework Quantity			n/a		
RM		n/a	0	0	0	Total Good		0			
WIP		n/a	0	0	0						
FG		n/a	0	0	0	Rework PPM (Good)		0			
B. Orie	ntation				•		•				
Date	2024-10-24			Time		11:41					
Title	e Orientation regarding to criticality of this item in scoring.				-1	ı					
Attend	Attendees Tooling Diecut Detaching										
Prepared By:					Approved By:						
GERALD DE GUZMAN 241128						REXEL ALMARIO 250205					



INVESTIGATION REPORT FORM (IRF)

1 dx 160. (615) 543-6302											
II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)											
Date Conducted: 2024-10-2	PIC: M.	PIC: M. ASIS									
Id	lentified Rootcause					Recomme	ndation				
Nick mark on the slot portion	on		Repairi	ng of the	die-blade						
III. CORRECTIVE ACTIO	N VERIEICATION (To	ho filled out k	w OA In cha	rao)							
III. CORRECTIVE ACTION	Checked By:	Date	Implemen		Running	JO Num	her	Date	NG Qty	Lot Qty	
1.1.1/	-					-			-	_	
1st Verification of Action	M. ASIS	2024-11-07	[/]Yes [1st	JO-F-24-9		241107	3	1000	
2nd Verification of Action			[] Yes [] No	2nd	JO-F-24-9	979-3	241108	0	1000	
3rd Verification of Action			[] Yes [] No	3rd	JO-F-24-1	.002-3	241113	0	4300	
Effectiveness of Action	M. ASIS	2024-12-07	[/]Yes [] No	4th	JO-F-24-1	.039-1	241126	0	4500	
Remarks: The corrective action implemented on-time was the repairing of the die-blade.											
					5th	JO-F-24-1	.085-1	241207	0	3000	
		IV	. CLOSURE								
Status		Remarks									
Closed IRF		Five consecutive lots running with only 3pcs NG.									
Approved by:				Process Owner Acknowledgment: (Receiving Section)							
			CED								
MICHAEL CASILLANO 25 12:52	KOHEI ISHI	KOHEI ISHII 250313 09:06		GERALD DE GUZMAN 250318 03:36			REXEL ALMARIO 250507 11:25				
QA Head	Тор М	Top Management			Line Leader			Department Head			
D . 05050505 00 10	D . 0505050	D. I. 25252525 02 12			D : 05050505 00 10			D . 05050505 05 07			