KANEPACKAGE PHILIPPINE INC.			INVESTIGATION REPORT FORM (IRF)						
Teleph	Ring Road LISP II, Bro one No. (049) 5457-7	Control	No.:	Date Issued					
Fax No. (049) 545-6302			0016		241011				
Customer	KOWA-EMORI PH	HILIPPINES, INC.	Attention To WEENA APALLA						
Item Code	HP33D1057-1 E0	QOS	Department	PRODUCTION	N				
Item Description	CARTON BOX		Date of Detection 241008						
Job Order Number	JO24-M-01612-9		Section Detected	ected QA SCREENING					
ı	ILLUSTRATION C	OF THE PROBLEM							
	S. (1)	Lot Quantity (pcs) Reject		Qty (pcs)	Reject %				
			3000	1	60	5.33			
193		,	Nature of Defect:						
	111		BURSTING ON EDGE						
-	The same of the sa	/	Requirement:						
			There should be no bursting						
			Actual						
		bursting T: No bursting	Bursting up to 20mm						
NO. OF OC	CURENCE	DISPOSITION	AREA OF OC	CURENCE / OR					
First		Hold	Slotter Gluing			Material			
Recurrence No.: 1		Special Acceptance For Rework	EQOS Diecut	Vertical		Dimension Appearance			
Date.: 241008		Reject / Disposal	Detaching Othe			Process / Method			
Issued by		Checked by	Approved by		Received by (Receiving Sec				
LESTER JOHN D	IOSO 241011	CHARLENE JAN MARIE FLORES 241011	MICHAEL CASILLA	ANO 241015	GERALD DE GUZMAN 241016				
		I. INVESTIGATION	/ ANALYSIS						
DIRECT CAUSE: (A	nalyze the reasor	of occurence, why it happened?)							
System / Training									
Design / Toolings									
Process / Material									



INVESTIGATION REPORT FORM (IRF)

Department Head

INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)											
Syste	m / Trai	ning									
Desigi	n / Tool	ings									
Proces	ss / Mat	terial									
CORRI	CTIVE	ACTION: (Action	a ta ba dana			ONCLUSION		and in)	WIIO / WIIFN		
						lem will not hap			WHO / WHEN		
IMME	DIATE A	CTION: (Action	to be done to	contain/ te	emporary cori	rect the problem	1 foun	nd)			
A. Sort	ing Resu	ult				C. Reworking					
		Location	Total Stock	NG	Total Good	Rework Quant	ity n/a		n/a		
RM		n/a	0	0	0	Total Good		0			
WIP		n/a	0	0	0						
FG		n/a	0	0	0	Rework PPM (Good)			0		
B. Orie	ntation		<u>'</u>		•						
Date				Time		08:10					
Title		Orientation regra	ading Bursting o	n Edge of K	lowa Emori HP3	3D1057 1 Carton	Box				
Attend	Attendees All Production										
Prepared By:					Approved By:						
GERALD DE GUZMAN 250128						REXEL ALMARIO 250205					



Date: 25252525-03-13

Date: 25252525-03-10

INVESTIGATION REPORT FORM (IRF)

II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)													
Date Conducted: 2024-10-11					PIC: M.ASIS								
Ic	lentified F	Rootcause					Recomme	ndation					
Movement of reverse creasing matrix during running.					N/A								
III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)													
	Che	ecked By:	Date	Im	plemented?	Running	JO Num	ber	Date	NG Qty	Lot Qty		
1st Verification of Action	I	M.ASIS	2024-11-06	[/]	Yes [] No	1st	JO24-M-02	017-28	241206	3	3000		
2nd Verification of Action]			Yes [] No	2nd	JO24-M-02	017-29	241210	20	4000		
3rd Verification of Action]			Yes [] No	3rd	JO24-M-020	017-55	241219	0	4000		
Effectiveness of Action M.ASIS 2025-01-06 [Yes [] No	4th	JO24-M-02	0	3500				
Remarks: Included the chec Set-up and Operation (WI-P													
						5th	JO24-M-02	413-31	250106	0	3000		
			IV	/ CLC	SURE								
Status						emarks							
Status	Status Remarks												
Closed IRF	Closed IRF Five consecutive lots running with minimal rejects only												
Approved by: Process Owner Acknowledgment: (Receiving So								Section)					
MICHAEL CASILLANO 250310 12:53 KOHEI ISHII 250313 09:07					GERALD DE GUZMAN 250318 03:36 REXEL ALMARIO 250507 1					11:25			
QA Head Top Management					Line Leader Department Head								

Date: 25252525-03-18

Date: 25252525-05-07