			INVESTIG	ATION R	EPORT	FORM (IRF)	
No. 5 Ring Road LISP II, B Clustomer Elephone No. (049) 5455-6302 Item Code 513850300 Item Description PAD, ASF Job Order Number JO-24-L-0225-1 IUSTRATION ISUE TERSTRATION ACCTUAL: 37mm-38r REQUIRE TENT: 400 NO. OF OCURENCE Image: Strate Strate Image: Strate Strate NO. OF OCURENCE Image: Strate Image: Strate Image: Strate Image: Strate Image: Strate Image: Strate Image: Strate	gy. La Mesa, Calamba City, Laguna '166 to 69	Control I	No.:	Date Issued			
Fax No	o. (049) 545-6302		0024			241026	
Customer	EPSON PRECISIC	ON PHILIPPINES INCORPORATED - IJP	Attention To	WEENA APAL	LA		
Item Code	513850300		Department	PRODUCTION	N		
Item Description	PAD, ASF		Date of Detection	241019			
Job Order Number	JO-24-L-0225-1		Section Detected	QA SCREENI	NG		
I	ILLUSTRATION C	OF THE PROBLEM					
h	1		Lot Quantity (pcs	s) Reject (Qty (pcs)	Reject %	
		-	2500	2	00.8		
Customer EPSON PRECISION PHILIPPINES INCORPORATED Item Code 513850300 item Description PAD, ASF lob Order Number JO-24-L-0225-1 ILLUSTRATION OF THE PROBLEM INCORPORATED OF THE PROBLEM INCORPORATED OF THE PROBLEM INCORPORATION INCORPORATION INCORPORATION OF THE PROBLEM INCORPORATION IN	3162	Nature of Defect:					
		-		OFF S	SPECS		
			Requirement:				
16				40mm tolera	nce: +/-1m	ım	
			Actual				
				37mm	-38mm		
NO. OF OC	CURENCE	DISPOSITION	AREA OF OCC	CURENCE / OR	IGIN	CONTENT	
First			Slotter	Gluing		Material	
Recurrence	No.:		EQOS Diecut	Vertical		Dimension Appearance	
	Date.: 241019		Detaching	Others SLICING	<u>.</u>	Process / Method	
Issue	d by	Checked by	Approved	l by	Received	by (Receiving Section)	
LESTER JOHN D	LESTER JOHN DIOSO 241026 CHARLENE JAN MARIE FLORES 241029		MICHAEL CASILLA	NO 241031	GERALD DE GUZMAN 241128		
		I. INVESTIGATION	/ ANALYSIS		L		
	nalyze the reason	n of occurence, why it happened?)					
System / Training							
Design / Toolings							
Process / Material							

Т

Г



KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 5457-7166 to 69 Fax No. (049) 545-6302

INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)

System / Training

Design / Toolings

Process / Material

FINAL CONCLUSION										
CORRE	CTIVE	ACTION: (Act	ions to be done	to ensure	that the prob	lem will not hap	pen again)	WHO / WHEN		
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)										
						C. Reworking				
		Location	Total Stock	NG	Total Good	Rework Quantity n/a		n/a		
RM		n/a	0	0	0	Total Good		0		
WIP		n/a	0	0	0					
FG		n/a	0	0	0	Rework PPM (Go	od)	0		
B. Orien	ntation		•				ŀ			
Date	2024-10-28					Time		10:33		
Title		Orientation regarding Off Specs of Epson 513850300 Pad ASF								
Attendees Slicing Vertical Pressing Heating operator										
Prepared By:						Approved By:				
GERALD DE GUZMAN 250128						REXEL ALMARIO 250205				
						Department Head				

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 5457-7166 to 69 Eax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Fax No. (049) 54	15-6302										
II. QA ROOTCAUSE VERI	FICATION	(To be fill	ed out by QA	In-char	ge)						
Date Conducted: 2024-12-04				PIC	C: L. Dioso						
Identified Rootcause					Recommendation						
The slicing discrepancy was of proper scrap thickness select	tion.			Ep	eran good scr		identification a on of work insti		faccepta	ole	
III. CORRECTIVE ACTION		ATION (To I ced By:	be filled out k	-	-charge) emented?	Running	JO Number	Date	NG Qty	Lot Qty	
1st Verification of Action	L. D	ioso	2024-12-04	[/]Ye	es []No	1st	JO-24-L-0243	-5 241204	0	2000	
2nd Verification of Action]			es []No	2nd	JO-24-L-0243	-7 241206	0	2000	
3rd Verification of Action				[]Ye	es []No	3rd	JO-24-L-0243	-6 241206	0	2000	
Effectiveness of Action	Effectiveness of Action			[]Ye	es []No	4th	JO-24-L-0243	-8 241211	0	3000	
Remarks: Corrective action v	vas effectiv	re.				5th	JO-24-L-0243	-9 241216	0	2000	
			١١	. CLOSI	URE						
Status Remarks											
Closed IRF	C	Corrective actions and operator awareness have been implemented to prevent recurrence and ensure proper material usage.									
Approved by:				Process Owner Acknowledgment: (Receiving Section)							
MICHAEL CASILLANO 250415 10:05 KOHEI ISHII 2504			I 250416 10:07	7	GERALD DE GUZMAN 250423 09:01			REXEL ALMARIO 250507 11:24			
QA Head Top Management				Line Leader			Department Head				
Date: 25252525-04-15 Date: 25252525-04-16					Date: 25252525-04-23 Date: 25252525-05-07						