| | | | _ | | | | | |
|--|--|--|---|---------------------|--|----------------------|--|--|
| | NEPACKAG | INVESTIGATION REPORT FORM (IRF) | | | | | | |
| | Ring Road LISP II, Broone No. (049) 5457-7 | Control I | No.: | [| Date Issued | | | |
| Fax No | . (049) 545-6302 | 0048 | | 250124 | | | | |
| Customer | CANON BUSINES | SS MACHINE PHILS. | Attention To REXEL ALMARIO | | | | | |
| Item Code | RX1-5781-000, F | RX1-5755-000 | Department | PRODUCTION | | | | |
| Item Description | | | Date of Detection | of Detection 250120 | | | | |
| Job Order Number | JO-TO-IPD-25-00 | Section Detected | QA SCREENING | | | | | |
| 1 | ILLUSTRATION C | OF THE PROBLEM | | | | | | |
| RX1-5755 | Hotel Ma | | Lot Quantity (pcs | Reject (| Qty (pcs) | Reject % | | |
| 110V | | 2400 | 5 | 50 2.08 | | | | |
| 6 18 1000 0 11 1000 0 11 | (IP) | 55 | Nature of Defect: | | | | | |
| Have the latest an expension of the second o | | PEEL OFF | | | | | | |
| がなっている場合をご問題を見る。からないできる。 をなったのか、ことのできる。 ないからないないできる。 ないからないないできる。 ないからないないできる。 ないないないないないないないないないないない。 というないないないないないないないないないないないないないないない。 というないないないないないないないないないないないないないないないないないないな | | Requirement: | | | | | | |
| | This printer is intended to a sow or reused HP data, are can ledge using a non-HP effects areas of these mean | The same of the sa | PEEL OFF UP TO 10 MM IS ACCEPTABLE (CLASS B) | | | | | |
| | 3PZ15-0 | Actual | | | | | | |
| | | PEEL OFF UP TO 20 MM | | | | | | |
| NO. OF OC | CURENCE | DISPOSITION | AREA OF OCC | CURENCE / OR | IGIN | CONTENT | | |
| First Recurrence No.: 1 Date.: 240120 | | Hold | Slotter Gluing EQOS Vertical Diecut Others Detaching Approved by | | Material Dimension | | | |
| | | Special Acceptance | | | | | | |
| | | For Rework Reject / Disposal | | | Appearance Process / Method Received by (Receiving Section) | | | |
| | | Checked by | | | | | | |
| MA. ERIKA MAE | - | CHARLENE JAN MARIE FLORES 250125 | MICHAEL CASILLANO 250127 | | GERALD DE GUZMAN 250128 | | | |
| THE ENTITY OF THE | 7.015 23012 | I. INVESTIGATION | | 10 230127 | GET WED T | 52 G02/M/(V 230120 | | |
| DIRECT CAUSE: (A | nalyze the reasor | of occurence, why it happened?) | ANALISIS | | | | | |
| System / Training | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Design / Toolings | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Process / Material | | | | | | | | |
| W1 Not fu | | Peel Off during auto stripping in Diecut S. | 1700. r nW2 Insufficie | nt pressure on t | he slot portion | on.rnW3 Over | | |
| | of Ejector Sponge. | 3 | | • | • | | | |



INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)

INVESTIGATION REPORT FORM (IRF)

| Syster | n / Trai | ning | | | | | | | | |
|---|----------|-----------------|-----------------|-------------|-----------------|------------------------|----------------------------------|--------------------|--|--|
| | | | | | | | | | | |
| Design | ı / Tool | ings | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Proces | s / Mat | terial | | | | | | | | |
| WHY 1 | : N/A | | | | | | | | | |
| | | | | | FINAL CO | NCLUSION | | | | |
| CORRE | CTIVE | ACTION: (Action | ns to be done | to ensure t | that the probl | lem will not hap | pen again) | WHO / WHEN | | |
| Proces | s / Mat | terial | | | | | | | | |
| WHY 1: Request for die blade re layout using Mizzoko white ejector sponge inside the slot and green ejector sponge with spacing outside the slot. Production Leaders // 2025-03- | | | | | | | Production Leaders // 2025-03-19 | | | |
| WHY 2: | TRAI | NING ON PROPER | R USAGE OF EJEC | CTOR SPONG | GE (CITO) FOR T | THE STANDARDIZA | ATION. | CITO // 2025-03-19 | | |
| IMMED | IATE A | CTION: (Action | to be done to | contain/ te | emporary cori | rect the problem | found) | | | |
| A. Sorting Result | | | | | C. Reworking | | | | | |
| | | Location | Total Stock | NG | Total Good | Rework Quant | ity | n/a | | |
| RM | | n/a | 0 | 0 | 0 | Total Good | | 0 | | |
| WIP | | n/a | 0 | 0 | 0 | | | | | |
| FG | | n/a | 0 | 0 | 0 | Rework PPM (Good) | | 0 | | |
| B. Orie | ntation | | | | | | | | | |
| Date 2025-03-19 | | | | | | Time | | 10:31 | | |
| Title CITO TRAINING | | | | | | | | | | |
| Attend | ees | PRODUCTION Q | A ME DESIGN | | | | | | | |
| Prepared By: | | | | | | Approved By: | | | | |
| GERALD DE GUZMAN 250410 | | | | | | REXEL ALMARIO 250507 | | | | |
| | | | | | | | Departme | nt Head | | |



INVESTIGATION REPORT FORM (IRF)

| II. QA ROOTCAUSE VEF | RIFICATION (To be fil | ed out by QA | In-charge) | | | | | | | | | |
|--------------------------------|------------------------|--|------------------|------------------------------------|------------------|-----------------|-----------------|---------|--|--|--|--|
| Date Conducted: 2025-01-2 | PIC: M.ASIS | PIC: M.ASIS | | | | | | | | | | |
| Į. | dentified Rootcause | | | Recommendation | | | | | | | | |
| Over application of Ejector | Request for die- | Request for die-blade re-layout | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| III. CORRECTIVE ACTIO | N VERIFICATION (To | be filled out k | oy QA In-charge) | | | | | | | | | |
| | Checked By: | Date | Implemented? | Running | JO Numb | er Date | NG Qty | Lot Qty | | | | |
| 1st Verification of Action | M.ASIS | 2025-03-18 | [/]Yes []No | 1st | JO-F-25-37 | 77-9 250403 | 3 1 | 600 | | | | |
| 2nd Verification of Action | | | [] Yes [] No | 2nd | JO-F-25-42 | 24-4 250412 | 2 14 | 1000 | | | | |
| 3rd Verification of Action | | | [] Yes [] No | 3rd | JO-F-25-46 | 52-2 25042 | L 0 | 1000 | | | | |
| Effectiveness of Action | | | [] Yes [] No | 4th | JO-F-25-55 | 8-2 250502 | 2 0 | 1000 | | | | |
| Remarks: | | | | | | | | | | | | |
| | | | | 5th | JO-F-25-46 | 250503 | 0 | 1500 | | | | |
| | | 1/ | /. CLOSURE | | | | | | | | | |
| Status | | Remarks | | | | | | | | | | |
| Status | | neilidiks | | | | | | | | | | |
| Still Open | nning with minimal def | g with minimal defects. Implemented corrective action is effective | | | | | | | | | | |
| · | | | | | | | | | | | | |
| | Approved by: | | Drago | as Owner A | alen avul a dama | ent. (Deseiving | Costian | | | | | |
| | | Process Owner Acknowledgment: (Receiving Section) | | | | | | | | | | |
| MICHAEL CASILLANO 2 07:47 | 50613 RHODORA | MIRANDA 25062 07:58 | | GERALD DE GUZMAN 250626 02:04 | | | N/A | | | | | |
| QA Head | Top N | /lanagement | Line | Line Leader | | | Department Head | | | | | |
| Date: 25252525-06-13 | Date: 2525252 | 25-06-26 | Date: 25252525 | Date: 25252525-06-26 | | | Date: - | | | | | |