KAN	INVESTIGATION REPORT FORM (IRF)									
No. 5 R Telepho	Control N	No.:	[	Date Issued						
Fax No. (049) 545-6302			0062		250222					
Customer	EPSON PRECISIO	ON PHILS. INC ASP/EPLB	Attention To	REXEL ALMARIO						
Item Code	511593800		Department PRODUCTION							
Item Description	OUTER CARTON	BOX	Date of Detection	250218						
Job Order Number	JO25-M-00652-4		Section Detected	QA SCREENI	NG					
I	LLUSTRATION C	OF THE PROBLEM								
HANDLE WITH CA			Lot Quantity (pcs	s) Reject (	Qty (pcs)	Reject %				
EPSON	re ⊈⊉1		1200	2	20	1.67				
EPSON	Nature of Defect:									
Made in	TORN									
			Requirement:							
			Acceptable up to 5mm							
			Actual							
		<mark>20mm-25mm</mark> ble up to 5mm	With torn up to 20mm-25mm							
NO. OF OC	CURENCE	DISPOSITION	AREA OF OCC	CURENCE / OR	RIGIN	CONTENT				
First		Hold	Slotter Gluing		Material					
Recurrence No.: 1		Special Acceptance	EQOS Diecut	Vertical		Dimension				
	Date.: 250218	Reject / Disposal	Detaching	Others HANDLING		Appearance Process / Method				
Issued	d by	Checked by	Approved	by Received		l by (Receiving Section)				
LESTER JOHN DI	OSO   250222	CHARLENE JAN MARIE FLORES   250225	MICHAEL CASILLA	NO   250226	GERALD	GERALD DE GUZMAN   250410				
		I. INVESTIGATION	ANALYSIS							
-	nalyze the reaso	n of occurence, why it happened?)								
System / Training WHY 1: DUE TO CR	OWDED AREA									
WHY 2 : DURING TRANSPORTATION THE ITEM COLLIDED WITH AN OBJECT										
WHY 3 : INSUFFICIENT PROTECTION ON THE EDGES OF THE ITEM										
Design / Toolings	Design / Toolings									
Process / Material										



## KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 5457-7166 to 69 Fax No. (049) 545-6302

	. ,									
INDIRECT C	AUSE: (Analyze	the reason of c	occurrence,	why it leake	d?)					
System / Ti	raining									
WHY1: n/a	a									
Docian / Ta	olings									
Design / To	onngs									
Process / M	laterial									
				FINAL CO	DNCLUSION					
CORRECTIV	'E ACTION: (Acti	ions to be done	to ensure	that the prob	lem will not happ	will not happen again) WHO / W				
System / Ti	raining									
WHY 1: PL	ITTING ADDITION	AL PROTECTION (	SCRAP) FOR	BIG SHEETS			Production Leaders // 2025-03-27			
IMMEDIATE	ACTION: (Actio	on to be done to	contain/ to	emporary cor	rect the problem	found)				
A. Sorting Re	esult				C. Reworking					
	Location	Total Stock	NG	Total Good	Rework Quantity	у	0			
RM	na	0	0	0	Total Good		0			
WIP	na	0	0	0						
FG	na	0	0	0	Rework PPM (Goo	od)	0			
B. Orientatio	n									
Date	Date 2025-03-27						08:15			
Title	Production Ass	sembly								
Attendees	production ope									
Prepared By:					Approved By:					
GERALD DE GUZMAN   250428					REXEL ALMARIO   250507					
						Departme	nt Head			

KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 5457-7166 to 69 Fax No. (049) 545-6302						INVESTIGATION REPORT FORM (IRF)							
II. QA ROOTCAUSE VER	IFICATI	ON (To be fil	led out by QA	ln-cha	arge)								
Date Conducted:	Date Conducted: PIC												
Id	lentified	Rootcause					Recomm	endation					
III. CORRECTIVE ACTIO	N VERIF	ICATION (To	be filled out	by QA	In-charge)								
	Ch	ecked By:	Date	Im	plemented?	Running	JO Nu	mber	Date	NG Qty	Lot Qty		
1st Verification of Action				[]	Yes [ ]No	1st							
2nd Verification of Action				[]	Yes [ ]No	2nd							
3rd Verification of Action				[ ] Yes [ ] No		3rd							
Effectiveness of Action	-			[ ]Yes [ ]No		4th							
Remarks:						5th							
		I	ľ	V. CLO	SURE								
Status		Remarks											
Still Open													
Approved by:					Process Owner Acknowledgment: (Receiving Section)								
N/A			N/A		N/A			N/A					
QA Head		Top Management			Line Leader			Department Head					
Date: - Date: -			1	Date: - Date: -									