

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 5457-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Control No.:

Date Issued

0080

250410

Customer	HIBLOW PHILIPPINES INC.	Attention To	REXEL ALMARIO
Item Code	DB04020110-00	Department	PRODUCTION
Item Description	Individual Box	Date of Detection	250330
Job Order Number	JO25-M-00996-9	Section Detected	QA SCREENING 2

ILLUSTRATION OF THE PROBLEM

ACTUAL: Exceed printing tolerance
REQUIREMENT: Printing tolerance ± 3

Lot Quantity (pcs)	Reject Qty (pcs)	Reject %
700	13	1.86

Nature of Defect:

MISALIGN PRINT

Requirement:

Printing tolerance ± 3

Actual

Exceed printing tolerance

NO. OF OCCURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN		CONTENT
<input checked="" type="checkbox"/> First <input type="checkbox"/> Recurrence No.: <u>1</u> Date.: <u>250330</u>	<input type="checkbox"/> Hold <input type="checkbox"/> Special Acceptance <input type="checkbox"/> For Rework <input checked="" type="checkbox"/> Reject / Disposal	<input type="checkbox"/> Slotter <input type="checkbox"/> EQOS <input checked="" type="checkbox"/> Diecut <input type="checkbox"/> Detaching	<input type="checkbox"/> Gluing <input type="checkbox"/> Vertical <input type="checkbox"/> Others	<input type="checkbox"/> Material <input type="checkbox"/> Dimension <input type="checkbox"/> Appearance <input checked="" type="checkbox"/> Process / Method
Issued by	Checked by	Approved by	Received by (Receiving Section)	
LESTER JOHN DIOSO 250410	CHARLENE JAN MARIE FLORES 250421	MICHAEL CASILLANO 250422	GERALD DE GUZMAN 250506	

I. INVESTIGATION / ANALYSIS**DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)****System / Training****Design / Toolings****Process / Material**

WHY 1 : Movement of print during process.

WHY 2 : Delayed timing/feeding of boards.

WHY 3 : Warp materials.

WHY 4 : Lacking of weight jig.

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 5457-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)****System / Training****Design / Toolings****Process / Material**

WHY 1 : na

FINAL CONCLUSION**CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)****WHO / WHEN****Process / Material**

WHY 1: Provision of new weight jig to prevent warping of materials. Paper weight jig already disposed as per advised of top management.

ME // 2025-06-30

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)**A. Sorting Result**

	Location	Total Stock	NG	Total Good
RM	na	0	0	0
WIP	na	0	0	0
FG	na	0	0	0

C. Reworking

Rework Quantity	na
Total Good	0
Rework PPM (Good)	0

B. Orientation

Date	2025-06-10	Time	09:01
Title	na		
Attendees	na		

Prepared By:**Approved By:**

GERALD DE GUZMAN | 250618

N/A

Department Head

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 5457-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)**

Date Conducted:	PIC:
Identified Rootcause	Recommendation

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked By:	Date	Implemented?	Running	JO Number	Date	NG Qty	Lot Qty
1st Verification of Action			[] Yes [] No	1st				
2nd Verification of Action			[] Yes [] No	2nd				
3rd Verification of Action			[] Yes [] No	3rd				
Effectiveness of Action			[] Yes [] No	4th				
Remarks:				5th				

IV. CLOSURE

Status	Remarks
Still Open	

Approved by:		Process Owner Acknowledgment: (Receiving Section)	
N/A	N/A	N/A	N/A
QA Head	Top Management	Line Leader	Department Head
Date: -	Date: -	Date: -	Date: -