## INVESTIGATION REPORT FOR DELAMINATION (516228900-LIONEL 2 MDL EUROPE)

DIRECT CAUSE METHOD / PROCESS

W1: Delamination occured due to insufficcient glue.

W2: Low level og glue in the container.

INDIRECT

Operators didn't perform proper checking of glue in the container

CAUSE METHOD
/ PROCESS

## PRODUCTION ACTION PLAN

**IMMEDIATE ACTION** 

Setting of standard level of glue in glue container

**CORRECTIVE ACTION:** 

Strictly checking of glue every after loading of SF.

Prepared by:

Reviewed by:

PRODUCTION IE TEAM Sir Marco Pesa

Noemi Cepeda
PRODUCTION SUPERVISOR