KANEPACKAGE PHILIPPINE INC.  No. 5 Ring Road LISP II, Brgy, La Mesa, Calamba City, Laguna					INVESTIGATION REPORT FORM (IRF)						
K	Telephone No.	(049) 545-7166 to		Inhouse Detection Customer Claim							
				Control No.: IRF-07-0007 Date Issued: 15-Jul-22							
Custome	omer EPPI IJP			Attention To NOEMI CEPEDA							
Item Co	em Code 5164438-01			Department KPLIMA-PRODUCTION							
Item De	scription	LUCIDA			Date of Detection 05-Jul-22						
Job Ord	er Number	-		Section Detected EPPI							
	ILL	USTRATION O	F THE PROBLEM		Major						
	Fax No. (049) 545-6302  tomer				Lot Quantity (pcs.) Reject Quantity (pcs.) Reject Percentage  124 3 2.42%  Nature of Defect:						
Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302  Customer    EPPI IJP				DETACHED							
	1		1	Requirement:							
					ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF DETACHED						
					Actual:						
	MAINT				DETACHED OCCURRED ON PAD BLOCKS TO PAD BLOCKS AND PAD BASE TO PAD BLOCKS						
NO. OF OCCURRENCE DISPO			DISPOSITION		AREA OF OCCURRENCE / ORIGIN CONTENT						
	First		Hold		Slotter	Gluing		Material			
П			Special Acceptance	$+\Box$	EQOS Vertical Dimens Diecut Others: Appear						
_			For Rework								
	Date:		Reject / Disposal		Detaching			Process / Method			
					Approved by Received by (Receiving Section)						
			QA Supervisor		QA Asst. Mana	inager		N. Cepeda Head/ Supervisor			
			I. INVESTIGA	ION / A							
		nalyze the reaso	on of occurrence, why it happened?)	Why 1:		: (Analyze the re	eason of occurr	ence, why it leaked?)			
gui											
Traini				Why 2:							
. / wa	200				Why 3:						
Syste	Why 4:				Why 4:						
	Why 5:				Why 5:						
S	Why 1:				Why 1:						
Design / Toolings	Why 2:				Why 2:						
n/T	Why 3:				Why 3:						
Desig	Why 4:				Why 4:						
	Why 5:				Why 5:						
-	Why 1:			Why 1:							
Process / Material	Why 2: Why 3:				Why 2:						
s/M					Why 3:						
oces	Why 4:			Why 4:							
١٠٠	Why 5:			Why 5:							

## R

## KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

## INVESTIGATION REPORT FORM (IRF)

				FINAL CON	CLUSION					
	OCCURRENC	DE ROOTCAUSE					OUTFLOW ROOTCAUSE			
IMMEDIATE ACTIO	N: (Action to be don	e to contain/ temporary	correct the pro	oblem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
. Sorting Result					Act	ions to be d	one to eliminate recurrence	Who / When		
	Location	Total Stock	NG	Total Good						
RM					System					
WIP										
FG										
B. Orientation										
Date Time		Time			Design / Tools					
Title					10018					
Attendees		Section Sept. House the								
C. Reworking								v 8		
Rework Quantity					Process					
Total Good										
Rework Percentage (Go				4.0000000000000000000000000000000000000						
II. QA ROOTCAU	ON (To be filled or	ut by QA In	-charge)	Date Conducted: PIC:						
	identille	ed Rootcause					Recommendation			
	76.10.00	III CORREC	CTIVE ACT	ON VERIEICATI	ON (To be filled o	out by QA li	n-charge)			
	Ch	SERVICE SERVICE	Date		nented?	out by wat ii	Remarks			
Checked by  1st Verification of Action				[ ] No		Nonland				
2nd Verification of Act	ion			[ ]Yes	[ ] No					
3rd Verification of Acti	ion			[ ]Yes	[ ] No					
Effectiveness of Action	on			[ ]Yes	[ ] No			8		
Note: If no same defe deliveries or 3rd verifi	ects / problems of ication of action s	ccurs for 5 consecu still not yet impleme	utive deliveri ented, Invesi	ies, corrective act tigation Report sh	tion is considered nall be re-issued to	effective / ci the affecte	losed. If the same problem oc d department to provide new	curs within 5 consecutive improvement action.		
				IV. CLC	OSURE					
Status:	Remark	s:		Appro	ved by:		Process Owner Acknowled	Igment: (Receiving Section		
Closed										
Still Open							1	1		
Re-Issue IRF			QA S	Supervisor	QA Asst. Ma	anager	Line Leader  Date:	Department Head  Date:		