	No. 5 Ring Re	oad LISP II, Brgy. L o. (049) 545-7166 t	SE PHILIPPINE INC. a. Mesa, Calamba City, Laguna o 69	INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: IRF-07-0011 Date Issued: 27-Jul-22					
Custom	er EPPI IJP				Attention To NOEMI CEPEDA				
Item Co	ode				Department KPLIMA-PRODUCTION				
Item De	escription PARTS BOX			Date of Detection 25-Jul-22					
Job Order Number 19035				Section Detected		INLINE QA			
	ILI	USTRATION O	F THE PROBLEM		Major Minor				
					t Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage		
					300	35	11.67%		
					Nature of Defect: BURSTING Requirement: ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF BURSTING Actual: BURSTING OCCURRED ON THE FOLDING SIDE				
NO. OF OCCURRENCE First Recurrence No.: Date:			DISPOSITION Hold Special Acceptance For Rework Reject / Disposal Checked by		CONTENT Material Dimension Appearance Process / Method Received by				
	C. Arevalo G. Magasino QA-IE Staff QA Supervisor				N. Cepeda QA Asst. Manager Head Supervisor				
			I. INVESTIGA	ION / AN	ALYSIS				
		Analyze the reaso	on of occurrence, why it happened?)		INDIRECT CAUS	E: (Analyze the reason of occu	rrence, why it leaked?)		
System / Training	Why 1: Why 2: Why 3: Why 4: Why 5:			Why 1: Why 2: Why 3: Why 4: Why 5:					
Design / Toolings	Why 1: Why 2: Why 3: Why 4: Why 5:	(x)	\$	Why 1: Why 2: Why 3: Why 4: Why 5:	Why 2: Why 3: Why 4:				
Process / Material	Why 1: Why 2: Why 3: Why 4: Why 5:		а.	Why 1: Why 2: Why 3: Why 4: Why 5:					

R

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

	x No. (049) 545-6302		No. of Park	FINAL CON	CLUSION				
	OCCURRE	ENCE ROOTCAUSE		TINAL CON	CEOSION		OUTFLOW ROOTCAUSE		
	OGGINA						000000000000000000000000000000000000000		
IMMEDIATE	ACTION: (Action to be	done to contain/ temporary	y correct the pro	oblem found)	CORREC	TIVE ACTION: (Actions to be done to ensure that the	problem will not happen again)	
Sorting Result							done to eliminate recurrence	Who / Whe	
	Location	Total Stock	NG	Total Good					
RM -					_				
WIP					System				
-G									
Orientation									
Date		Time			Design /				
Title					Tools				
Attendees									
Reworking									
Rework Quantity					Process				
otal Good									
Rework Percenta	age (Good)								
II. QA RO	OTCAUSE VERIFICA	ATION (To be filled o	ut by QA In	-charge)	Date Conduc	ted:	PIC:		
	Ident	tified Rootcause			Recommendation				
		III. CORRE	CTIVE ACTI	ON VERIFICATI	ON (To be fi	led out by QA I	n-charge)		
Checked by		Date	Implemented?			Remarks			
1st Verification	1st Verification of Action		[]Yes []No				,		
2nd Verification of Action		[]Yes []No							
3rd Verification of Action			[]Yes []No					ži	
Effectiveness	of Action			[]Yes	[] No				
Note: If no san deliveries or 3	ne defects / problems d verification of actio	s occurs for 5 consect n still not yet impleme	utive deliveri ented, Invest	es, corrective act igation Report sh	ion is considerall be re-issu	ered effective / co ed to the affecte	osed. If the same problem oc d department to provide new	curs within 5 consecutive improvement action.	
				IV. CLC	DSURE			(李) [[]	
Status:	Remarks:			Appro	ed by:		Process Owner Acknowledgment: (Receiving Section		
Closed									
Still Open			QA S	Supervisor	QA As	st. Manager	Line Leader	Department Head	
Re-Issue IRF			Date:		Date:		Date:	Date:	