KANEPACKAGE PHILIPPINE INC.  No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69					INVESTIGATION REPORT FORM (IRF)  Inhouse Detection Customer Claim					
	Fax No. (049)			Control	Control No.: IRF-24-01-0001 Date Issued: 10-Jan-24					
Custome	er	EPPI		Attention	n To	N. CEPEDA/ R.	I. CEPEDA/ R. ALMARIO			
Item Code 5151436-00				Departn	Department KPLIMA- PRODUCTION					
Item Description CARTON BOX STD;B				Date of	Date of Detection 240108 NS					
Job Order Number 053256			Section Detected INLINE QA/M3							
ILLUSTRATION OF THE PROBLEM					Major Minor					
					t Quantity (pcs.)	Reject Qua	antity (pcs.)	Reject Percentage		
8					299	1	5	5.02%		
100249 NOSd3 FOOU Trojector EPS EXGEED YOU					Nature of Defect:  PEEL-OFF					
	n 1		-0	ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF PEEL OFF						
			, <u>«</u>	Actual:	Actual:					
					PEEL OFF WAS ENCOUNTERED ON THE ITEM (PLEASE SEE ATTACHED PICTURE)					
	NO. OF OCCURRENCE		DISPOSITION			Slotter		CONTENT		
	First		Hold		Slotter	Gluing		Material		
	Recurrence		Special Acceptance		EQOS	Vertic	al	Dimension		
	No.: For Rework				Diecut	Others	s:	Appearance		
	Date:		Reject / Disposal	2	Detaching		Process / Method			
	Issued by		Checked by		Approved	by		Received by (Receiving Section)		
J. Japay QA/IE Staff			G. Massino QA Supervisor		QA Asst. Ma	nager	N. Cepedar R. Almario ger Head/ Supervisor/ Manager			
			I. INVESTIG	ATION / A						
	DIRECT CAUSE: (A	Analyze the reason	on of occurrence, why it happened?)		INDIRECT CAL	JSE: (Analyze the r	eason of occurr	ence, why it leaked?)		
Đ.	Why 1:			Why 1:						
rainir	Why 2:				Why 2:					
System / Training	Why 3:			Why 3:	Why 3:					
	Why 4:				Why 4:					
	Why 5:			Why 5:						
Design / Toolings	Why 1:			Why 1:						
	Why 2:				Why 2:					
	Why 3:				Why 3:					
	Why 4:				Why 4:					
	Why 5:				Why 5:					
Process / Material	Why 1:			Why 1:						
	Why 2:			Why 2:						
	Why 3:				Why 3:					
Proce	Why 4:				Why 4:					
1	Why 5:			Why 5:	Why 5:					

## KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

## **INVESTIGATION REPORT FORM (IRF)**

				FINAL CO	NCLUSION					
100	ОС	CURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE			
IMMEDIATE	E ACTION: (Act	ion to be done to contain/ tempora	ry correct the pro	oblem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
A. Sorting Result					Actions to be done to eliminate recurrence Who / When					
	Locati	on Total Stock	NG	Total Good						
RM										
WIP					System					
FG										
3. Orientation										
Date		Time			Design /					
Title					Tools					
Attendees										
C. Reworking					2- 1- 1		- 0.00-30-30			
Rework Quantity	у				Process			15		
Total Good					FIOCESS					
Rework Percent	tage (Good)					1				
II. QA RO	OTCAUSE VE	RIFICATION (To be filled o	out by QA In	-charge)	Date Conducted:_		PIC:			
		Identified Rootcause					Recommendation			
		III. CORR	ECTIVE ACT	ION VERIFICAT	TION (To be filled o	out by QA	In-charge)			
		Checked by	Date		nented?		Remarks			
1st Verification	1st Verification of Action		[ ]Yes		[ ]No					
2nd Verification of Action		[ ]Yes		[ ]No						
3rd Verification of Action		[ ] Yes		[ ] No						
Effectiveness of Action			[ ]Yes		[ ] No					
Note: If no sai deliveries or 3	me defects / pr ard verification	oblems occurs for 5 consectors action still not yet implement	utive deliverie ented, Investi	es, corrective act igation Report sh	tion is considered e hall be re-issued to	ffective / cl the affecte	osed. If the same problem occu d department to provide new im	rs within 5 consecutive provement action.		
		A LANGE OF		IV. CL	OSURE					
Status:		Remarks:		Appro	ved by:		Process Owner Acknowledg	ment: (Receiving Section)		
Closed										
Still Open			QA S	Supervisor	QA Asst. Mar	nager	Line Leader	Department Head		
Re-Issue IRF			Date:		Date:		Date:	Date:		